

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N078432465

FACILITY: MOYLE CONCRETE - ONTONAGON		SRN / ID: N0784
LOCATION: 49953 GREENLAND RD, ONTONAGON		DISTRICT: Upper Peninsula
CITY: ONTONAGON		COUNTY: ONTONAGON
CONTACT: JON LABYAK , PLANT MANAGER		ACTIVITY DATE: 11/06/2015
STAFF: Joe Scanlan	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Unannounced inspection of concrete batch plant to determine compliance with PTI# 247-84.		
RESOLVED COMPLAINTS:		

FACILITY: *Ontonagon Concrete Batch Plant—Moyle Concrete, Inc.*

INSPECTION DATE: 11/6/2015

MDEQ-AQD STAFF

- *Joseph Scanlan, EQA*

FACILITY REPRESENTATIVE

- *NA*

LOCATION

This facility is located on M-38 about 1.8 miles east of the city of Ontonagon (49953 Greenland Road) and is mostly rural; however there are two single-family residences to the east and west that are approximately 200' and 400' from the plant, respectively.

SOURCE DESCRIPTION

This is a concrete batch plant.

INSPECTION

On 11/06/2015 I conducted an unscheduled visit of Moyle Concrete, Inc.'s Ontonagon concrete batch plant. PPE worn during this inspection included steel-toed boots, safety vest, safety glasses and hardhat. PTI# 247-84 was originally issued to Bob's Redi-Mix Concrete in 1986, however it was transferred to Moyle Concrete, Inc., in April of 1995.

This facility is vacant and it is apparent that it has not operated in quite some time. The driveway is gated and the parking/walking area around the facility is overgrown with vegetation. The facility does appear operable and turn-key ready.

SPECIAL CONDITIONS PTI#247-84

- Rule 331 – The particulate emission from the cement handling and storage operations shall not exceed 0.10 lbs per 1000 lbs of exhaust gases, calculated on a dry gas basis;
- Visible emissions from the cement handling and storage operations shall not exceed a 6-minute average of 20% opacity, except as specified in Rule 301(1)(a);
- Applicant shall not operate the concrete batch plant unless the fabric filter collector is installed and operating properly.

SUMMARY

The facility is vacant however it does appear operable and turn-key ready. No violations of PTI# 247-84 were observed at the time of this inspection and the facility appears to be in compliance with the permit.



Image 1(MC1) : Front of facility from M-38 (Greenland Road). Offices are in the building frame right.




Image 2(MC2) : Enclosed load-out area, with doors open



Image 3(MC3) : Load-out bins and chute




Image 4(MC4) : Overgrown vegetation at site--no activity apparent



Image 5(MC5) : Overgrown vegetation at site--no activity apparent



Image 6(MC6) : Overgrown vegetation at site--no activity apparent

NAME Joseph S. Sander

DATE 12/16/15

SUPERVISOR _____