

STAFF REPORT

Michigan Department of Environment, Great Lakes, and Energy

- | | | | |
|---|--|---|--|
| <input type="checkbox"/> Hazardous Waste/Pt.111 | <input type="checkbox"/> Liquid Ind.Waste/Pt.121 | <input type="checkbox"/> Complaint Inspection | <input type="checkbox"/> Corrective Action |
| <input type="checkbox"/> Solid Waste/Pt.115 | <input type="checkbox"/> Scrap tire/Pt.169 | <input checked="" type="checkbox"/> Compliance Inspection | <input type="checkbox"/> Sampling Inspection |
| | <input type="checkbox"/> Other _____ | <input type="checkbox"/> Construction/Closure Inspection | <input type="checkbox"/> Telephone Call |
| | | <input type="checkbox"/> Permitting Inspection | <input type="checkbox"/> Meeting Notes |
| | | <input type="checkbox"/> PEAS Investigation | <input type="checkbox"/> Other _____ |

Facility/Site Name Arbor Hills Landfill	Date/Time 11-17-2023 8:55am to 10:40am
Address 10699 W. Six Mile Road	Facility/Site Number WDS 475946
Participants/Contacts Anthony Testa	Staff Gary Schwerin

REFERRED TO:
REMARKS (weather, unusual conditions, etc.): 57 ⁰ , overcast, wind SW 5mph. Times rounded to the nearest 5 minutes.
After receiving numerous odor complaints, I completed an odor inspection near Arbor Hills Landfill.
I completed inspections and made the noted observations at the following locations:
50595 Northstar Way – No landfill odor at 8.55am
17475 Briar Ridge Land – Medium intensity (2.5) compost odor at 9:00am
50508 Tamarack Trail – Light (2) compost odor at 9:10am. 50500 Tamarack Trail was complaint address but not located.
49109 Freestone Drive – Light (2) Landfill gas odor at 9:20 am
16327 Johnson Creek Drive – No landfill odor at 9:30am
638 North Center – No landfill odor at 9:45am
111 Baseline Road – No landfill odor at 9:50am
21520 Chubb Road – No landfill odor at 10:05am
50937 Briar Ridge Lane – No landfill odor at 10:20am
Light (2) compost odor on Napier Road south of 6-Mile Road between the 2 northernmost air monitors. I noticed 4 fans I believe are the “odor mitigating fans” used by the landfill, but they were not operating at 10:35am
Light (2) compost odor on 6-Mile Road between Napier Road and the compost area drive at 10:40am.

