## DEPARTMENT OF ENVIRONMENTAL QUALITY

## AIR QUALITY DIVISION

## FCE Summary Report

DUNTY LANE			DFILL/MAN			эп	N :	N36	34
90 CAMP RC	DAD					Dis	strict :	Cad	lillac
						Co	unty :	MAI	NISTEE
IISTEE	State:	MI	Zip Code :	49660			9	Cor	npliance
MAJOR					Staf	if:	Rob Di	ckma	n
३ : 8/1/2015							pletion		8/3/2016
	90 CAMP RC	90 CAMP ROAD IISTEE State: MAJOR	90 CAMP ROAD IISTEE State: MI MAJOR	90 CAMP ROAD IISTEE State: MI Zip Code : MAJOR	90 CAMP ROAD IISTEE State: MI Zip Code : 49660 MAJOR	90 CAMP ROAD IISTEE State: MI Zip Code : 49660 Comp Status MAJOR Stat 9 : 8/1/2015 FCE	90 CAMP ROAD Dis Co IISTEE State: MI Zip Code : 49660 Compliance Status : MAJOR Staff :	90 CAMP ROAD District :   IISTEE State: MI Zip Code : 49660 Compliance Status :   MAJOR Staff : Rob Di   9: 8/1/2015 FCE Completion	90 CAMP ROAD   District : Cac     0 County : MA   County : MA     IISTEE   State: MI Zip Code : 49660   Compliance Cor     MAJOR   Staff : Rob Dickma     9: 8/1/2015   FCE Completion

## List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments		
06/20/2016	ROP Other	Compliance	Malfunction of the sulfur treatment system caused H2S gas to be sent directly to the flare in excess of permitted limits (400 ppm post treatment). Pursuant to the MAP for the facility, this incident was reported to me via email on 6/11/16. The result of the incident was gas at 7,000 PPM H2S at 893 CFM released to the flare and a mass emission of SO2 of 0.59 tons post flare. The facility took prompt action to report and correct this malfunction. No further action is recommended.		
03/23/2016	ROP Annual Cert	Compliance	Report appears complete. Two deviations regarding the flow meter not recording at several different times in the last year. Total time the meter was not reading was approximately 7 days for the past year. No further action is recommended.		
03/23/2016	ROP SEMI 2 CERT	Compliance	Report appears complete. One deviation regarding the flow meter not recording at several different times in the last six months. Total time the meter was not reading was approximately 10 hours for the past six months. No further action is recommended.		
03/22/2016	MAERS	Compliance	See MAERS database for further info.		

Activity Date	Activity Type	Compliance Status	Comments			
10/05/2015	ROP Semi 1 Cert		Malfunctions of the flow meter due to condensation during winter months.			

Name: Date: 8/9/16 Supervisor: Page

.