. . \_ . . \_ . . . . . .

## DEPARTMENT OF ENVIRONMENTAL QUALITY **AIR QUALITY DIVISION ACTIVITY REPORT: On-site Inspection**

N589761083		
FACILITY: MDNR GAYLORD REPAIR FACILITY		SRN / ID: N5897
LOCATION: 540 S OTSEGO AVE, GAYLORD		DISTRICT: Gaylord
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 12/08/2021
STAFF: Sharon LeBlanc	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: On-Site inspection for permitted ground water remediation site located at South Otsego Ave and Fifth, Gaylord Michigan.sgl		
RESOLVED COMPLAINTS:		

On Wednesday, December 8, 2021, AQD District Staff stopped at the former MDNR Gaylord Repair Facility located at 540 S. Otsego Ave, Gaylord, Michigan. The referenced facility was permitted for a ground water remediation system.

Discussions with the RRD Staff at the Gaylord District Office indicated that cleanup activities for MDNR Facilities is handled by MDNR. Per the May 28, 2015, site inspection report, the monitoring well network and remediation system were still onsite for potential future use.

An attempt was made to contact MDNR staff identified in the 2015 inspection report as being associated with the site. However, those person(s) have left State employ. A review of the Otsego County Property Appraisers office info indicates that the site is presently owned by the county.

During the onsite visit it was noted that two buildings exist on the property of interest, one is a Federal Communications tower with associated and fenced building. The other is a small wooden shed on a concrete slab. The monitoring well network is no longer present on the property.

District Staff stopped into Wilburs Auto Parts, located immediately south of the site, and spoke with staff who indicated that the equipment, and the monitoring well network were "all removed years ago". District Staff will be following up with MDNR and Otsego County staff to confirm that the equipment was removed from site. sgl

NAME

DATE \_\_\_\_\_\_ SUPERVISOR \_\_\_\_\_