

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N611359656

FACILITY: BREITBURN OPERATING LP - SMC PHASE 2		SRN / ID: N6113
LOCATION: SE SE SEC 33 T31N R1W, CHARLTON TWP		DISTRICT: Gaylord
CITY: CHARLTON TWP		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 09/01/2021
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: FY21 scheduled inspection		
RESOLVED COMPLAINTS:		

Traveled to N6113 Breitburn SMC Phase 2 CPF for a scheduled inspection to determine compliance with PTI 671-96. This was the second attempt to access the source due to the locked gate limiting access to this location.

This facility must have a key to access. The site is located inside the Whitetail Hunts Grand View Ranch (989-732-2978) on Sparr Rd. To use the Ranch driveway to enter, a keypad code is required. To access without the code, drive through the Core Energy LLC Charlton 28 CPF (NE SE SE Sec 28 31N 1W) site just east of the Ranch. At the back of the Core CPF property is a 10 foot tall gate which needs to be unlocked with a key from OGMD or Breitburn. A bar in the middle of the gate must be lifted, and then a metal bracket at the hinge lifted, in order to open the gate. The gate must be closed immediately after opening. Once inside the Ranch property, travel south, at the split in the road, continue left. Follow past the pond and the CPF will be on the right, approximately 1 mile from the entrance gate.

A Caterpillar engine and small dehy were onsite, along with several small oil tanks for servicing the equipment. The CPF was not operating during the inspection. There is a pump jack located outside the building that was also not operating. There is a lined tank farm on the west side of the building with two tank approximately 400 bbl in size.

Records were reviewed separately. Based on the onsite inspection, the facility appears to be in compliance with their permit.

NAME _____

DATE _____

SUPERVISOR _____