

From: Chris Gordon <detroitwilbertcremation@yahoo.com>
Sent: Thursday, August 10, 2023 11:22 AM
To: Reid, Marie (EGLE) <ReidM5@michigan.gov>
Subject: Re: : N7548 Detroit Wilbert Cremation Services VN 7-17-2023

Hello Marie, there was a miscommunication. I set the temp to 1650 degrees for the secondary chamber on the machine while you two were at my location. Both of you watched me do it, so I thought we were all set. I apologize. The only reason the temperature was lower than 1600 is because I thought that the preheat requirement was 1400 degrees. The air actuator problem didn't keep me from reaching that temperature, the problem it caused was more fluctuation than normal causing a see-saw effect on the chart recorder. So, the problem was corrected before you left and the air actuator has since been replaced. Here are a couple of pics of more recent chart records. Hopefully this is sufficient for you. If you need anything else let me know.

Thank you, Chris Gordon



