

STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY

LANSING DISTRICT OFFICE



SRN: A2809, Lapeer County

February 15, 2022

Mr. Kirk Payne, Director of Sales Mold Masters Company 1455 Imlay City Road Lapeer, Michigan 48446

Dear Mr. Payne:

VIOLATION NOTICE

On January 31 and February 11, 2022, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD), was contacted by Mold Masters Company (Mold Masters) located at 1455 Imlay City Road, Lapeer, Michigan. The purpose of these contacts, through email and by telephone, was to discuss Mold Masters' compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Air Pollution Control Rules; and the conditions of Permit to Install (PTI) number 368-06D, and Consent Order AQD No. 2020-19.

As a result of these discussions, staff have determined the following:

	Rule/Permit	
Process Description	Condition Violated	Comments
EUFlockBooth5	PTI No. 368-06D, Special	Failure to submit a Malfunction
	Condition (SC) III 4	Abatement Plan (MAP) within 180
		days from commencemet of trial
		operation of the Regenerative
		Thermal Oxidizer (RTO).
EUFlockBooth5	PTI No. 368-06D, SC IV. 3;	Failure to operate RTO in a
	Rule 910	satisfactory manner, based on
		VOC destruction efficiency not
		meeting minimum-required 95
		percent (by weight), during
		preliminary testing.
EUFlockBooth5	PTI No. 368-06D, SC V. 2	Failure to test within 180 days from
		commencement of trial operation
		of the RTO to verify VOC
		destruction efficiency.
EUFlockBooth5	PTI No. 368-06D, SC V. 3	Failure to test within 180 days from
		commencement of trial operation
		of EUFlockBooth5 to verify the
		associated enclosure meets the
		definition of Permanent Total
		Enclosure (PTE).
EUFlockBooth5	PTI No. 368-06D, SC VII. 1	Failure to notify AQD in writing of
		the completion of installation or
		construction of the PTE and RTO.

Mr. Kirk Payne Mold Masters Company Page 2 February 15, 2022

PTI No. 368-06D, Special Condition (SC) III. 4 requires that within 180 days from commencement of trial operation of the Regenerative Thermal Oxidizer (RTO) associated with EUFlockBooth5, Mold Masters submit, implement, and maintain a malfunction abatement plan (MAP), as described in Michigan Air Pollution Control Rule 911. The commencement date of trial operation of the RTO was communicated to me today, to be February of 2021. As of February 1, 2022, AQD has not received a MAP from Mold Masters, in violation of this requirement.

PTI No. 368-06D, SC IV. 3 requires that Mold Masters not operate EUFlockBooth5 unless the RTO and associated Permanent Total Enclosure (PTE) are installed, maintained, and operated in a satisfactory manner, with satisfactory operation of the RTO including, but not limited to, a minimum volatile organic compound (VOC) destruction efficiency (DE) of 95 percent (by weight). It was reported to AQD that preliminary stack testing on January 31, 2022, resulted in a DE of 94-95 percent, and that in September 2021, a preliminary stack test resulted in a DE of 74 percent. These values do not indicate satisfactory operation of the RTO, and thus, are in violation of this condition.

The failure to operate the RTO in a satisfactory manner also constitutes a violation of Rule 910 of the administrative rules promulgated under Act 451, which requires that an air-cleaning device be installed, maintained, and operated in a satisfactory manner and in accordance with the administrative rules and existing law.

PTI number 368-06D, SC V. 2 requires that within 180 days from commencement of trial operation of the RTO associated with EUFlockBooth5, Mold Masters shall verify the VOC DE of the RTO by testing. Stack testing did not occur within the required 180 days, in violation of this condition.

PTI No. 368-08D, SC V. 3 requires that within 180 days from commencement of trial operation of EUFlockBooth5, the permittee shall verify that the associated enclosure meets the definition of PTE or verify capture efficiency of the enclosure by testing. Neither verification that the associated enclosure meets the definition of PTE, nor verification of the capture efficiency of the enclosure by testing were completed during the required 180 days in violation of this condition.

PTI No. 368-06D, SC VII. 1 requires that within 30 days after completion of the installation, construction, reconstruction, relocation or modification of the PTE and RTO associated with EUFlockBooth5, Mold Masters or their authorized agent shall notify the AQD District Supervisor, in writing, of the completion of the activity. Completion of the installation, construction, reconstruction, relocation, or modification is considered to occur no later than the commencement of trial operation of the PTE and RTO associated with EUFlockBooth5. AQD has not received written notification and therefore Mold Masters is in violation of this requirement.

Please initiate actions necessary to correct the cited violations and submit a written response to this Violation Notice by March 8, 2022, (which coincides with 21 calendar days from the date of this letter). The written response should include: the dates the violations occurred; an explanation of the causes and duration of the violations; whether the violations are ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the

Mr. Kirk Payne Mold Masters Company Page 3 February 15, 2022

violations and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

Please submit the written response to EGLE, AQD, Lansing District, at P.O. Box 30242, Constitution Hall, 1st Floor South, Lansing, Michigan 48909 and submit a copy to Ms. Jenine Camilleri, Enforcement Unit Supervisor at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760.

In addition to the written response above, please provide to the AQD, Lansing District a copy of 12-month rolling calculations of individual and total hazardous air pollutants for FGFACILITY, since the RTO and PTE began operating, and 12-month rolling calculations of VOC emissions for EUFlockBooth5, since the RTO and PTE began operating.

If Mold Masters believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violations cited above and for your cooperation in these matters. If you have any questions regarding the violations or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely,

Daniel A. McGeen Environmental Quality Analyst Air Quality Division 517-648-7547

cc: Ms. Mary Ann Dolehanty, EGLE Dr. Eduardo Olaguer, EGLE Ms. Jenine Camilleri, EGLE Mr. Christopher Ethridge, EGLE Mr. Brad Myott, EGLE