DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility :	NEENAH PAPER - MICHIGAN INC			SRN:	B1470			
Location: 501 E MUNISING AVE						District :	Upper Peninsula	
							County:	ALGER
City: N	IUNISING	State:	MI	Zip Code :	49862	Comp	liance	Compliance
Source Clas	s: MAJOR					Staf	f: Joel A	sher
FCE Begin I	Date: 1/1/2014					FCE Date	Completion	12/21/2015
Comments :	FCE compl	eted 12/	21/2	015. JA				

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
12/21/2015	Scheduled Inspection	Compliance	Annual inspection. Full Compliance Evaluation.
09/18/2015 ROP Semi 1 Cer		Compliance	Semi-Annual Report Certification from January 1, 2015 through June 30, 2015
09/18/2015	CAM Excursions/Exceedan ces	Compliance	Other: MDEQ Compliance Assurance Monitoring (CAM) Excursion/Exceedance Summary Report Form for stated period 1/1/2015 - 06/30/2015
09/18/2015	CAM monitor downtime	Compliance	CAM Monitor Downtime Incident Summary Report Form submitted for 1/1/2015 to 6/30/2015.
03/05/2015	ROP SEMI 2 CERT	Compliance	Semi-annual Certification Compliance Report submitted for period 7/1/2014 to 12/31/2014.
03/05/2015	ROP Annual Cert	Compliance	Annual Compliance Certification Report submitted for 2014.
03/05/2015	CAM Excursions/Exceedan ces	Compliance	CAM certification submitted.
03/05/2015	CAM monitor downtime	Compliance	CAM Monitor Downtime Certification submitted.
10/30/2014	CAM Excursions/Exceedan ces	Compliance	CAM Excursion/Exceedance Summary Report Form submitted for first half of 2014.
10/30/2014	CAM monitor downtime	Compliance	CAM Monitor Downtime Incident Summary Report Form submitted for first half of 2014.
09/22/2014 ROP Semi 1 Cert		Compliance	Semi-annual certification report submitted for period from 1/1/2014 to 6/30/2014.

Activity Date	Activity Type	Compliance Status	Comments
03/13/2014	ROP SEMI 2 CERT	Compliance	Company reported 9 deviations: 3 were for scheduled filter audits, 2 were for switching from coal to natural gas causing the baghouse to go into bypass, 2 were for annual "off-stack" calibration by a 3rd party, 1 was for cleaning of the opacity monitor and the last one was to remove a rock from the stoker resulting in an uneven distribution of coal on the ash bed.
03/13/2014	ROP Annual Cert	Compliance	See semi-annual reports for descriptions of deviations.

Name: Date: 12/28/15 Supervisor: Page 2 of 2