


- PLAN/



STEELTECH
Improve your bottom line.

June 23, 2014

Eric Grinstern
Senior Environmental Quality Analyst
Air Quality Division
State Office Bldg.
350 Ottawa NW, Unit 10
Grand Rapids, MI 49503-2341



Dear Mr. Grinstern,

The enclosed documentation is being sent to abate the cited violation from your visit to our foundry on June 5, 2014. Upon inspection following your visit, it was determined that the "cans" that support the bags from within had broken and punctured one of the bags. This allowed dust to escape through that hole.

We ordered all new cans and bags on June 6, 2014. They were shipped to us and arrived on June 20, 2014. Our Maintenance team installed them on Saturday, June 21, 2014. There are pictures showing the team at work replacing the "cans" (cylindrically shaped wire units) and the bags.

The dust control unit is now fully functional and no longer leaking dust.

Steeltech Ltd. is committed to being a responsible corporate citizen and we will do our utmost to maintain our compliance with state requirements.

Respectfully,

Greg Schuetz
Human Resources Director
Steeltech Ltd.
1251 Phillips Ave. SW
Grand Rapids, MI 49507
616-243-7920
gschuetz@steeltechltd.com