




201 S. Delaney Rd.
Owosso, MI 48867
April 27, 2020



Shiawassee

To whom it may concern:

This letter is in response to Daniel A. McGeen's observation from his inspection on September 12, 2019 of our Detrex VS 2000 batch vapor degreaser. The idle mode cover would not seal properly & he said the crumbling trim strips constitute defects. Please note that the cover is only closed when not in use. During the day, the cover is open when loading & unloading product.

Since his observation, we have made numerous attempts to the company who installed the unit originally to have the cover repaired & have had no success. We took it upon ourselves to repair the door using a high temperature rated & chemical resistant rubber seal. Attached are before & after photos. The degreaser operator will monitor the seal & report further defects if they should occur so it can be repaired in a timely manner.


The next step is to eliminate the need of the degreaser all together & it is already in the works. We are changing our parts & processes so degreasing will not be required. Our hope is to have it transitioned within a year.

Also, as a precaution, we had an air sampling submitted to Analytical Laboratory in February. An Organic Vapor Badge was worn by the degreaser operator for an eight-hour period. The results were excellent @ 16 ppm.

I hope this response answers any questions. Thank you for your time.

Sincerely,

Lisa Fisher, Materials Coordinator
Allied Motion Owosso
989-725-5151 ext 546



Before



After