

STAFF REPORT

Michigan Department of Environment, Great Lakes, and Energy

- | | | | |
|---|--|---|--|
| <input type="checkbox"/> Hazardous Waste/Pt.111 | <input type="checkbox"/> Liquid Ind.Waste/Pt.121 | <input type="checkbox"/> Complaint Inspection | <input type="checkbox"/> Corrective Action |
| <input type="checkbox"/> Solid Waste/Pt.115 | <input type="checkbox"/> Scrap tire/Pt.169 | <input checked="" type="checkbox"/> Compliance Inspection | <input type="checkbox"/> Sampling Inspection |
| | <input type="checkbox"/> Other _____ | <input type="checkbox"/> Construction/Closure Inspection | <input type="checkbox"/> Telephone Call |
| | | <input type="checkbox"/> Permitting Inspection | <input type="checkbox"/> Meeting Notes |
| | | <input type="checkbox"/> PEAS Investigation | <input type="checkbox"/> Other _____ |

Facility/Site Name Arbor Hills Landfill	Date/Time 12-7-23 5:30am to 7:30am
Address 10699 W. Six Mile Road	Facility/Site Number WDS 475946
Participants/Contacts Anthony Testa	Staff Gary Schwerin

REFERRED TO:
REMARKS (weather, unusual conditions, etc.): 35 ⁰ , partly cloudy, wind SW 5mph. Times are rounded to the nearest 5 minutes.
I arrived on-site at 5:30am to evaluate the effectiveness of the odor mitigating fans during operation start-up.
Light (2) landfill gas odor on Napier downwind from the Cell 6 sump area at 5:30am.
Landfill entrance gate unlocked at 5:40am.
Landfill staff began removing daily cover at 5:45am, fans are not running.
Trucks began unloading at 6:00am.
Strong (3) landfill gas odor on Napier downwind from the Cell 6 sump area at 6:00am. Fans are not running.
Medium (2.5) intensity garbage/landfill gas odor on 6-Mile downwind from active dumping area at 6:10am.
Strong (3) garbage/landfill gas odor on 6-Mile downwind from active dumping area at 6:20am.
Strong (3) landfill gas odor on Napier downwind from the Cell 6 sump area at 6:30am. Fans are not running.
Strong (3) garbage/landfill gas odor on 6-Mile downwind from active dumping area at 6:45am.
Strong (3) landfill gas odor on Napier downwind from the Cell 6 sump area at 6:50am. Fans are not running.
Strong (3) garbage/landfill gas odor on 6-Mile downwind from active dumping area at 7:20am.
Strong (3) landfill gas odor on Napier downwind from the Cell 6 sump area at 7:25am. Fans are not running.
The odor mitigating fans are not located downwind from the active filling area and would be ineffective in mitigating any odors generated at the active filling area.
I left at 7:30am

