

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N385666711

FACILITY: SERMACOAT		SRN / ID: N3856
LOCATION: 60 SUMMIT STREET, BRIGHTON		DISTRICT: Lansing
CITY: BRIGHTON		COUNTY: LIVINGSTON
CONTACT:		ACTIVITY DATE: 03/09/2023
STAFF: David Rauch	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: An unannounced routine inspection of the facility to check on PTI 474-93B.		
RESOLVED COMPLAINTS:		

Arrived at 60 Summit St at approximately 9:30am. Upon my arrival there were multiple cars in the parking lot but the work vehicles had the logo Spirit & Sons, Inc. when I walked into the building I was met by a worker named Josh who stated that the building is used for commercial roofing and metal trim. Josh showed me around the facility and ensured that the company did not have the permitted equipment I was looking for. This inspection was initially chosen to check on the emission unit under PTI 474-93B for the company Sermacoat at 60 Summit St. The equipment that was permitted was a Pre-Treatment Oven and Two Batch Curing Ovens. The permit also talked about Spray Line 1 and 2, Spray Booth 1 and DIP Coating. When I arrived at the site all the permitted equipment was removed and Sermacoat was no longer in business. The new company that occupied the building is a roofing company and does not have emission units outside of their buildings furnace. After a walk through of the building and a conversation with Josh, it was determined this facility was not an EGLE AQD source and Sermacoat would be closed and the permits voided to prevent further confusion.

After my visit with Spirit & Sons, Inc. I left to the parent company of Sermacoat Michigan Coatings Ventures at 160 Summit St. When I arrived on site, I was met by Mark Tomasik the QA and Environmental Vice President for Michigan Coatings Ventures. Mark and I discussed Sermacoat and how the facility was closed and all of the permitted equipment was no longer in use. Mark stated that the equipment I was looking for had been dismantled and taken apart. We also went through all the permits that were at the Michigan Coatings site and none of them were the 474-93B. Mark stated that Sermacoat had also moved to 1279 Rickett Rd in the past but was no longer there. He stated the building was converted into a new business called Work Skills. I left the facility and headed to 1279 Rickett Rd to ensure Sermacoat and all equipment were no longer on site. When I arrived the facility was operating as Work Skills and there was no permitted equipment on site.

In conclusion, Sermacoat's PTI 474-93B will be voided and the facility will be documented as closed in our records.

NAME David RauchDATE 03/21/2023SUPERVISOR RB