

STATE OF MICHIGAN

DEPARTMENT OF ENVIRONMENTAL QUALITY



C. HEIDI GRETHER
DIRECTOR

Lansing

August 3, 2016

Mr. Juan Reyes Air Technology Systems, Inc. 18016 Lasher Road Detroit, Michigan 48219

Ms. Pura Bascos Detroit Land Bank Authority 500 Griswold Street, Suite 1100 Detroit, Michigan 48226 Mr. James Wright
Detroit Building Authority
500 Griswold Street, Suite 1200
Detroit, Michigan 48226

Ms. Iva Patterson
City of Detroit
Office of Contracting & Procurement
1301 Third Street, 6th Floor
Detroit, Michigan 48226

SRN: U812608629

Dear Ms. Bascos, Ms. Patterson, Messrs. Juan and Wright:

VIOLATION NOTICE

On August 2, 2016, the Michigan Department of Environmental Quality (DEQ), Air Quality Division (AQD), performed an asbestos inspection at 8242 Faust and also at 8269 Faust, Detroit, Wayne County, Michigan. The purpose of this inspection was to determine compliance with the requirements of Title 40 of the Code of Federal Regulations, Part 61, Subpart M (National Emission Standard for Asbestos), and Rule 942 of Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended.

According to our investigation, the Detroit Land Bank Authority owns the properties and Air Technology Systems Incorporated performed the abatement activities at both of the sites. The City of Detroit Office of Contracting and Procurement, is the contract holder for the demolition and abatement, and the Detroit Building Authority oversaw the City of Detroit's demolition program. The vacant residences were abated as part of a project to remove blight within the City of Detroit. The National Emission Standard for Asbestos holds both the owner and operator equally liable for violations.

During the investigation, DEQ/AQD staff Jeremiah Brown and Karen Kajiya-Mills observed the following:

The subject properties had been abated and regulated asbestos-containing material (RACM) was discovered at the property.

Process Description	Section Violated	Comments
Failure to remove RACM duct wrap at 8242 & 8269 Faust, Detroit, Michigan.	§61.145(b)(4)(vi)	Failure to estimate the amount of Regulated Asbestos-Containing Material (RACM)
	§61.145(c)(1)	Failure to remove RACM

Please initiate actions necessary to correct the cited violation and submit a written response to this violation notice by August 24, 2016, (which coincides with 21 calendar days from the date of this letter). The written response should include: the date(s) the violation occurred; an explanation of the causes and duration of the violation; whether the violation is ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violation, and the date(s) by which these actions will take place; and what steps are being taken to prevent a reoccurrence. The signed written response from both owner and operator to this violation notice may be submitted by mail and directed to my attention at; DEQ AQD, P.O. Box 30260, Lansing, Michigan 48909 or scanned and sent as an email attachment to brownj9@michigan.gov.

If you believe the above observations or statements are inaccurate or do not constitute a violation of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violation cited above and for the cooperation extended to me during our meeting and emails. If you have any questions regarding the violation notice or the actions necessary to bring this facility into compliance, please contact me at 517-599-7825; browni9@michigan.gov; or DEQ AQD, P.O. Box 30260, Lansing, Michigan 48909-7760.

Sincerely,

Jeremiah Brown

Environmental Quality Analyst

Air Quality Division

cc: Dr. Abdul El-Sayed

Mr. Butch Hollowell

Ms. Lynn Fiedler, DEQ

Ms. Teresa Seidel, DEQ

Ms. Heidi Hollenbach, DEQ

Ms. Wilhemina McLemore, DEQ

Mr. Tom Hess, DEQ

Ms. Karen Kajiya-Mills, DEQ