STATE OF MICHIGAN

DEPARTMENT OF ENVIRONMENTAL QUALITY



DAN WYANT DIRECTOR

August 14, 2015

Mr. Jesse Brown Brown Environmental Construction 2389 E Outer Drive Detroit MI 48234-1958

Mr. Kevin Simowski Detroit Land Bank Authority 65 Cadillac Square, Suite 3200 Detroit, MI 48226

7007 2680 0002 1436 3416

7007 2680 0002 1436 3409

SRN: U821505094, Wayne County

Dear Mr. Brown and Mr. Simowski,

## VIOLATION NOTICE

On June 18, the Department of Environmental Quality (DEQ), Air Quality Division, conducted an inspection of several residential properties located in the City of Detroit. The properties are 17534 McDougall, 13784 Gable, 13984 Lumpkin, 17450 Joseph Campau, 14350 Minock, 16716 Dolphin and 14200 Evergreen, Detroit. The purpose of this inspection was to determine Brown Environmental Construction's compliance with the requirements of Title 40 of the Code of Federal Regulations, Part 61, Subpart M (National Emission Standard for Asbestos), and Rule 942 of Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended.

According to our investigation, the Detroit Land Bank Authority owns the properties, and Brown Environmental Construction performed demolition/renovation activities at the properties. The National Emission Standard for Asbestos holds both the owner and operator(s) equally liable for violations.

On June 18, 2015, AQD inspector Tammy S. Bell inspected several residential properties. Regulated-asbestos containing material (plaster) was identified at the 13984 Lumpkin site. The material was dry and friable. Regulated-asbestos containing material was also identified at 13784 Gable (skimcoat on wallboard). The material was dry and friable. Regulated-asbestos containing material (exterior caulk/sealant debris) was found dry and The homes had been demolished and the debris was still on friable at 17534 McDougall. site.

| <b>Process Description</b>   | Section Violated  | Comments  |
|--|---|---|
| Asbestos-NESHAP<br>subject residential   | §61.145(a), DEQ AQD Consent<br>Order No. 25-2013.       | Failure to thoroughly inspect for asbestos.   |
| properties located at<br>13984 Lumpkin, 17534<br>McDougall and 13784<br>Gable, Detroit | §61.145(b)(4)(vi), DEQ AQD Consent<br>Order No. 25-2013 | Failure to estimate the<br>amount of Regulated<br>Asbestos-Containing<br>Material (RACM). |

CADILLAC PLACE • 3058 WEST GRAND BOULEVARD • SUITE 2-300 • DETROIT, MICHIGAN 48202-6058 www.michigan.gov/deg • (313) 456-4700



Mr. Jesse Brown Mr. Kevin Simowski Page 2 August 14, 2015

| §61.145(c)(1), DEQ AQD Consent<br>Order No. 25-2013.    | Failure to remove RACM prior to demolition.               |
|---|---|
| §61.145(c)(4), DEQ AQD Consent<br>Order No. 25-2013.    | Failure to contain in leak tight container.               |
| §61.145(c)(6)(i), DEQ AQD Consent<br>Order No. 25-2013. | Failure to wet RACM that has been stripped.               |
| §61.150(b)(1), DEQ AQD Consent<br>Order No. 25-2013.    | Failure to dispose of<br>debris at a Type II<br>landfill. |

Please initiate actions necessary to correct the cited violations and submit a written response to this Violation Notice by September 4, 2015 (which coincides with 21 calendar days from the date of this letter). The written response should include: the dates the violations occurred; an explanation of the causes and duration of the violations; whether the violations are ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violations and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

If Brown Environmental Construction and/or the Detroit Land Bank Authority believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violations cited above and for the cooperation that was extended to me during our investigation. If you have any questions regarding the violations or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely.

Tammy S. Bell Sr. Environmental Quality Analyst Air Quality Division 313-330-0105

Enclosure: Sample results cc: Ms. Lynn Fiedler, DEQ Ms. Barb Rosenbaum, DEQ Ms. Teresa Seidel, DEQ Mr. Thomas Hess, DEQ Ms. Karen Kajiya-Mills, DEQ Ms. Wilhemina McLemore, DEQ