

M4159
MAWILADEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

M415973731

FACILITY: HENRY FORD HEALTH		SRN / ID: M4159
LOCATION: 1150 ELIJAH MCCOY DRIVE, DETROIT		DISTRICT: Detroit
CITY: DETROIT		COUNTY: WAYNE
CONTACT: Chris Slowinsky ,		ACTIVITY DATE: 09/23/2024
STAFF: Jill Zimmerman	COMPLIANCE STATUS: Non Compliance	SOURCE CLASS: MINOR
SUBJECT: Target Inspection		
RESOLVED COMPLAINTS:		

DATE OF INSPECTION : 9/23/2024

TIME OF INSPECTION : 11:00 am

INSPECTED BY : Jill Zimmerman

PERSONNEL PRESENT : Chris Slowinsky, Metropolitan Detroit Area Hospital Services, Inc

Dave Haas, General Manager Metropolitan Detroit Area Hospital Services, Inc

Janet Canty, Henry Ford

FACILITY PHONE NUMBER : 313-916-1414, Henry Ford

248-804-3866, Henry Ford

313-834-6500, MDAHs

EMAIL ADDRESS : chriss@mdahs.org

Jcanty1@hfhs.org

FACILITY BACKGROUND

The facility is two businesses housed in one building. Half of the building is used for Henry Ford Hospital main corporate offices. The rest of the building is leased by Metropolitan Detroit Area Hospital Services, Inc (MDAHS), which is a laundry facility contacted to preform laundry for Henry Ford Hospitals.

REQUIRED PPE

During the onsite inspection, I wore steel toed shoes, eye protection and a safety vest.

COMPLAINT/COMPLIANCE HISTORY

No complaints have been received regarding this facility.

OUTSTANDING VNs

NA

PROCESS EQUIPMENT AND CONTROLS

The Henry Ford side is primarily office space, though it is permitted for an emergency generator.

The MDAHS is leased by Henry Ford Hospital and is used to launder various hospital linen such as hospital gowns, towels and other materials used in the medical industry. The facility is currently unpermitted. The facility operates one emergency generator with an associated diesel tank, eighteen dryers, five washers and one steam tunnel.

INSPECTION NARRATIVE

I arrived at the facility, and I met with Mr. Dave Haas, and Mr. Chris Slowinsky from MDAHS. Mr. Haas and Mr. Slowinsky explained that they were associated with the laundry side of the facility and explained this process to me.

The security guard referred me to Mohammad (248-804-3866) who is responsible for operating and maintaining for the generator permitted and operated by Henry Ford. I called Mohammad who said that he was not responsible for maintaining the records for the generator. He referred me to Ms. Janet Canty (313-916-1414) with Henry Ford. I called Ms. Canty, whose voicemail directed me to email my response. I sent an email, which is attached to this report. As of the writing of this report, I have not received a response from Ms. Canty.

Ms. Haas and Mr. Slowinsky walked me through the laundry side of the facility and explained the process. Both the generator for MDAHS and Henry Ford are located side by side and were not operating during the onsite inspection. The laundry facility appeared to be operating properly.

APPLICABLE RULES/PERMIT CONDITIONS

MDAHS currently is operating without any permits. A letter requesting their potential to emit will be sent to the facility to determine if a permit is needed for the dryers in the laundry process, which includes eighteen dryers, five washer, and one steam tunnel. The facility has one 2 megawatt generator with an associated 4150 gallon diesel storage tank.

The generator for Henry Ford was not operating during the onsite inspection. It appeared to be properly maintained. No records were collected because Ms. Janet Canty has yet to respond to my email. Therefore I am unable to determine compliance with the permit.

EMISSIONS REPORT REVIEW


NA

FINAL COMPLIANCE DETERMINATION


Henry Ford does not appear to be operating in compliance with their permit conditions since I was never supplied with the requested records.

Metropolitan Detroit Area Hospital Services appears to need a permit for the emergency generator. A permit may also be needed for the laundry process. A determination for whether a permit is needed for the laundry process will be made once the Potential To Emit calculation are submitted.

NAME



DATE



SUPERVISOR

