

## Dow Corning Midland Plant Fugitive Dust Program


The following is proposed as the minimum treatment schedule

Control Method	Frequency	Area
Power flushing or street sweeper	Three times per year in May, July and September. *	<u>Paved Roads</u> A Road B Road C Road 2 Road 3 Road 4 Road 5 Road 300 Bk. Alley
Power flushing or street sweeper	Once in April or May	<u>Paved Lots</u> North 208/214 Main 114A South 5107
Applying CaCl <sub>2</sub> dust Suppressent**	Once a Month April 1 thru Oct. 31	<u>Unpaved roads &amp; parking areas in normal traffic areas</u> 119 Lot 500 Road 4704 Lots 2410 Road N.E. 2602 E. 2703 700 Lot 2700 Lot Contractors Lot Fence Line
Applying CaCl <sub>2</sub> dust Suppressent**	Once a Month April 1 thru Oct. 31	Landfill access road and normal traffic areas in the landfill

\* Service Department will monitor the condition of the roads and will power flush the roads additional times as nessary.

\*\* Verification of CaCl<sub>2</sub> application is done by Enviromental Services.

# DOW CORNING BRINE MAP



TRUCK 1  
TRUCK 2