

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : Hutchinson Antivibration Systems, Inc.	SRN : E5094
Location : 460 Fuller Ave. NE	District : Grand Rapids
	County : KENT
City : GRAND RAPIDS State: MI Zip Code : 49503	Compliance Status : Non Compliance
Source Class : MAJOR	Staff : David Morgan
FCE Begin Date : 8/1/2020	FCE Completion Date : 9/24/2021
Comments :	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
09/23/2021	ROP Semi 1 Cert	Non Compliance	Postmarked 9-15-21. Company reported deviations for not conducting RTO interlock testing and for fugitive emission observations around booths. A violation will be cited for not conducting interlock testing of the RTO which is important for ensuring control device operations.
09/23/2021	CAM Excursions/Exceedances	Compliance	Postmarked 9-15-21. No excursions reported.
09/23/2021	CAM monitor downtime	Compliance	Postmarked 9-15-21. No monitor downtime reported.
09/23/2021	MACT (Part 63)	Compliance	Postmarked 9-15-21 - Semiannual Compliance with Subpart M MMM. No deviations from Subpart M MMM were reported.
09/08/2021	ROP Annual Cert	Compliance	Post marked 3-15-2021. Deviations were reported but were being addressed by the company.
09/08/2021	ROP SEMI 2 CERT	Compliance	Post marked 3-15-2021. Deviations were reported but were being addressed by the company.
08/04/2021	On-site Inspection	Non Compliance	
05/03/2021	MAERS	Compliance	ROP Certification form for MAERS received 3-15-21. Emissions reported were as expected. This MAERS is acceptable. -DLM
04/28/2021	MACT (Part 63)	Compliance	Annual Compliance with Subpart D D D D D. No deviations from Subpart D D D D D were reported.

Activity Date	Activity Type	Compliance Status	Comments
04/28/2021	MACT (Part 63)	Compliance	Semiannual Compliance with Subpart M MMM. No deviations from Subpart M MMM were reported.
04/28/2021	CAM Excursions/Exceedances	Compliance	The company reported no excursions or exceedances.
04/28/2021	CAM monitor downtime	Compliance	The company reported no monitor downtime.
12/28/2020	ROP Semi 1 Cert	Compliance	Postmarked 9-15-20. Deviations reported for times when the CPMS data stored indicated values outside the appropriate operating limit. This was due to computer hardware and software problems that the company remedied in May 2020. Hutchinson verified that despite data problems, interlocks would have prevented the units from actually operating outside of parameter range. Hutchinson is working with programmers for improvements to the system to better document interlock function.
12/28/2020	CAM Excursions/Exceedances	Compliance	Postmarked 9-15-20. No excursions reported.
12/28/2020	CAM monitor downtime	Compliance	Postmarked 9-15-20. No monitor downtime reported.
12/28/2020	MACT (Part 63)	Compliance	Postmarked 9-15-20 - Semiannual Compliance with Subpart M MMM. No deviations from Subpart M MMM were reported.

Name: David L. Bryan

Date: 9/24/2021

Supervisor: HH