Project: EGLE Violation Notice Remediation Plan Notice #: SRN: N1022, Wayne County Inspection Date: August 28, 2023 Notice Date: September 29, 2023 Target Completion Date: November 15, 2023 EGLE Representatives: Eric Grinstern, Jill Zimmerman

 \sim

Metaltec Steel Abrasive Company Violation Remediation Action Plan



GOAL: Respond to and address each of the 5 items outlined in the EGLE Violation Notice letter by October 20, 2023 and complete them by November 15, 2023

Violation Process Rule Violate	Remediation Plan Description	Actions Taken to Date	Target Date / Actual Comp Date
Failure to maintain the fabric collector with an alarm that sounds when the pressure drop exceeds 5 inches of water. EUGRITPROCESS PTI No. 258-07, EUGRITPROCESS, Special Condition 1.3	Replace existing alarm on Grit Plant; East Baghouse with working alarm that sounds when pressure drop exceeds 5" W.P.	On 09/08/2023 new Dwyer A-285 remote alarm annunciators were purchased for the North, West and East baghouses. Shipping date is stated by the manufacturer to be approximately 11/01/2023.	11-03-2023 /
Visible emission readings conducted via Method 9 during the inspection exceeded a six-minute average of 5 percent opacity. A six-minute average of 35 percent was documented. FGFOUNDRYNORTH PTi No. 258-07, FGFOUNDRYNORTH, Special Condition 2.2	Investigate reason(s) for visible emission readings exceeding 5% opacity (35%) during the inspection	Without the north baghouse running and the south furnace pouring, a lot of smoke was generated that had nowhere to go other than out the openings of the building. To prevent this from occurring even when all conditions are normal, ductwork is being examined for buildup, and scrap bay doors will be lowered to mitigate excessive visible emissions from doors and openings, should the occur	09-05-2023 /

Project: EGLE Violation Notice Remediation Plan Notice #: SRN: N1022, Wayne County Inspection Date: August 28, 2023 Notice Date: September 29, 2023 Target Completion Date: November 15, 2023 EGLE Representatives: Eric Grinstern, Jill Zimmerman

Metaltec Steel Abrasive Company Violation Remediation Action Plan



GOAL: Respond to and address each of the 5 items outlined in the EGLE Violation Notice letter by October 20, 2023 and complete them by November 15, 2023

Violation Process Rule Violate	Remediation Plan Description	Actions Taken to Date	Target Date / Actual Comp Date
Failure to maintain the fabric collector with an alarm that sounds when the pressure drop exceeds 5 inches of water. The furnace was operating while the baghouse was not operational. FGFOUNDRYNORTH PTI No. 258-07, FGFOUNDRYNORTH, Special Condition 2.3	Replace existing alarm on North Foundry; North Baghouse with working alarm that sound when pressure drop exceeds 5" W.P.	On 09/08/2023 new Dwyer A-285 remote alarm annunciators were purchased for the North, West and East baghouses. Shipping date is stated by the manufacturer to be approximately 11/01/2023.	11-03-2023 /
Failure to maintain the fabric collector with an alarm that sounds when the pressure drop exceeds 5 inches of water. The furnace was operating without capture to the baghouse. FGFOUNDRYSOUTH PTI No. 258-07, FGFOUNDRYSOUTH, Special Condition 3.3	Replace existing alarm on South Foundry; West Baghouse with working alarm that sound when pressure drop exceeds 5" W.P.	On 09/08/2023 new Dwyer A-285 remote alarm annunciators were purchased for the North, West and East baghouses. Shipping date is stated by the manufacturer to be approximately 11/01/2023.	11-03-2023 /

Project: EGLE Violation Notice Remediation Plan Notice #: SRN: N1022, Wayne County Inspection Date: August 28, 2023 Notice Date: September 29, 2023 Target Completion Date: November 15, 2023 EGLE Representatives: Eric Grinstern, Jill Zimmerman

مالمحسو

ъ.

Metaltec Steel Abrasive Company Violation Remediation Action Plan



GOAL: Respond to and address each of the 5 items outlined in the EGLE Violation Notice letter by October 20, 2023 and complete them by November 15, 2023

Violation Process Rule Violate	Remediation Plan Description	Actions Taken to Date	Target Date / Actual Comp Date
Failure to take appropriate action procedures in accordance with the facility Malfunction Abatement Plan when the baghouse associated with FGFURNACENORTH malfunctioned. FGFACILITY PTI No. 258-07, FGFACILITY, Special Condition 4.4	1 Steer is at 5100 degrees 1 and the pouring process	Although the atomization process was not shut down as explained, overall production <i>was</i> shut down vis-a-vie the shot dryer not in operation and is an integral part of the steel shot production process. To prevent this occurrence in future, the P.M. program for the baghouses is being reviewed and "v-belt replacement" will be analyzed and adjusted to decrease time between replacement	10-30-2023 /