BREITBURN

|                      | RECEIVED<br>DEQ/AQD |
|----------------------|---------------------|
|                      | APR 02 2015         |
| MACES<br>MASAS<br>CC | FILE;               |

March 31, 2015

Ms. Caryn Owens MDEQ-Air Quality Division Cadillac District Office 120 West Chapin Street Cadillac, MI 49601-2158

RE: LOV for Permit #75-12 SRN #N6345 Garfield 1-/2-8

Dear Ms. Owens:

This letter is in response to a Violation Notice received on March 23, 2015 for the above referenced source. Although, Breitburn does not believe this to be a violation, the language in the PM/MAP needed updating to address the situation where a temperature rise across the catalyst is not measured but emission targets are still being achieved. Accordingly, we have attached a revised PM/MAP for this location.

We have been closely monitoring the operations of this engine, months prior to your records request. We've had emissions tests in an inverted temperature scenario as well as testing at normal temperatures. All testing showed no abnormal conditions of the 3 way catalyst.

Please contact me should you need any further information.

Sincerely,

Carolann Knapp' EH&S Regional Rep

Enclosure

BREITBURN ENERGY PARTNERS