

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility :	Metaldyne Powertrain Components, Inc.	SRN :	A1403
Location :	917 ANDERSON RD	District :	Jackson
		County :	HILLSDALE
City :	LITCHFIELD	State:	MI
Zip Code :	49252	Compliance Status :	Compliance
Source Class :	SM OPT OUT	Staff :	Brian Carley
FCE Begin Date :	6/2/2013	FCE Completion Date :	6/11/2014
Comments :			

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
06/11/2014	Scheduled Inspection	Compliance	Scheduled Inspection
03/17/2014	MAERS	Compliance	Timely. Accepted

Name:

Brian Carley

Date:

9/23/14

Supervisor:

[Signature]