DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: Scheduled Inspection

A403336447

FACILITY: The Dow Chemical Company U.S.A., Midland		SRN / ID: A4033
LOCATION: 1790 Building, MIDLAND		DISTRICT: Saginaw Bay
CITY: MIDLAND		COUNTY: MIDLAND
CONTACT: Kayla Peacock , Environmental Specialist		ACTIVITY DATE: 07/27/2016
STAFF: Kathy Brewer	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MEGASITE
SUBJECT: FGOSWRO		
RESOLVED COMPLAINTS:		

FGOSWRO -S1

The flexible group consists of the EU32INCINERATOR-S1 (hazardous waste incinerator), EUB7-S1 (incinerator complex tank farm), and EUC3-S1 (WWT P including wastewater sludge drying) subject to 40 CFR 63 Subpart DD - Offsite Waste and recovery operations MACT.

The emission units were all inspected as part of the Dow Chemical FCE. Records review and site inspection did not find any non compliance with applicable MACT standards.