

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : Midwest Rubber Company	SRN : A6444
Location : 3525 RANGELINE RD P.O. Box 98	District : Saginaw Bay
	County : SANILAC
City : DECKERVILLE State: MI Zip Code : 48427	Compliance Status : Non Compliance
Source Class : SM OPT OUT	Staff : Sydney Bruestle
FCE Begin Date : 4/5/2014	FCE Completion Date : 2/8/2016
Comments : VOC content of several coatings and materials exceed limits in PTI 375-97A and 259-04 a VN was sent. During the onsite inspection February 3, 2016 Midwest Rubber was found to be in compliance with all other permits and air quality rules.	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
02/03/2016	Scheduled Inspection	Non Compliance	Onsite inspection to evaluate compliance with Active PTIs: 383-86, 387-86, 388-86, 196-87, 567-94, 373-97, 375-97A, 376-97, 259-04, and 276-06

Name: *Sydney Bruestle* **Date:** 02/08/16 **Supervisor:** *C. Dale*