## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

## **FCE Summary Report**

Facility :	General Motors LLC Flint Metal Center					SRN:	B1608
Location: G-2238 Bristol Rd Mail Code 485-401-210					District :	Lansing	
						County:	GENESEE
City: F	LINT	State: M	Zip Code :	48553	Comp Status		Compliance
Source Class: MAJOR Staff: Daniel McGeen							
FCE Begin Date : 6/14/2019 FCE Completion 9/15/2020 Date :							
Comments :							

## **List of Partial Compliance Evaluations:**

Activity Date	Activity Type	Compliance Status	Comments
09/11/2020	MACT (Part 63)	Compliance	Semi-Annual Compliance report for MI-ROP-B1608-2016, FG-MACT LIGHT DUTY, VII.4 and 40 CFR Part 63, Subpart IIII, Section 63.3120 (a). No deviations were reported. Note: As of the 8/19/2020 PCE inspection of FMC, sealer operations had been moved to Flint Assembly, and the only sealer cell remaining at FMC was undergoing decommissioning.
09/11/2020	ROP Semi 1 Cert	Compliance	Semi-Annual report. No deviations were reported.
08/19/2020	Scheduled Inspection	Compliance	Scheduled inspection and review of facility recordkeeping, which are both partial compliance evaluation (PCE) activities, conducted as part of a full compliance evaluation (FCE).
05/08/2020	MAERS	Compliance	Report for 2019 operating year received timely & complete; passed audit. Reported emissions and material usage complied with limits in Rules 290 and 287, respectively, which are incorporated in ROP.
05/08/2020	MAERS	Compliance	2019 MAERS received electronically. Received timely and complete. Reported emissions were below what is allowed by the ROP, and by Rules 287 and 290.

Activity Date	Activity Type	Compliance Status	Comments
04/24/2020	ROP Semi 1 Cert	Compliance	Semi-Annual Report required by MI-ROP-B1608-2016, received timely and complete 9/5/2019. No deviations reported.
04/24/2020	MACT (Part 63)	Compliance	Semi-Annual Compliance Report received 3/16/2020, FG-MACT LIGHT DUTY, 40 CFR Part 63, Subpart IIII, Section 63.3120(a). The plant has sealer application subject to emission limit. No deviations from emission limit or work practices reported.
04/24/2020	ROP Annual Cert	Compliance	Annual Compliance Report MI-ROP-B1608-2016 received timely and complete 3/16/2020. A single deviation was reported; required annual maintenance on EU-FIREPUMP was not completed by 11/1/2019 (the required 365 days plus one month window since the 10/1/2018 maintenance) due to employee strike, and vendor becoming backed up on fire pump testing/maintenance at several other facilities. The maintenance was completed on 11/27/2019, however.
04/24/2020	ROP SEMI 2 CERT	Compliance	Semi-Annual Compliance Report MI-ROP-B1608-2016 received timely and complete 3/16/2020. A single deviation was reported; required annual maintenance on EU-FIREPUMP was not completed by 11/1/2019 (the required 365 days plus one month window since the 10/1/2018 maintenance) due to employee strike, and vendor becoming backed up on fire pump testing/maintenance at several other facilities. The maintenance was completed on 11/27/2019, however.

Activity Date	Activity Type	Compliance Status	Comments
04/23/2020	Other Non ROP	Compliance	On 4/23/2020, AQD received emailed Boiler MACT tune-up update letter from GM Flint Metal Center, indicating the tune-ups will be done on 4/27/2020, ahead of the 5/20/2020 deadline they would have under the MACT (within 61 months of the previous tune-up completion dates of 4/20-21/2015). A subsequent emailed letter on 4/24/2020 moved the date back to 4/29/2020, to ensure that GM would have time to implement new safety measures to prevent the spread of COVID-19, before people enter the site.
04/17/2020	MACT (Part 63)	Compliance	AutoMACT Semi-Annual report received timely and complete on 9/5/2019. Required by FG-MACT LIGHT DUTY, VII.4 and , 40 CFR Part 63, Subpart IIII, section 63.3120(a). The plant has sealer application subject to emission limit. No deviations from emission limit or work practices reported.
03/31/2020	Other	Compliance	AQD email of 3/30/2020 replied to Flint Metal Center 3/24 letter requesting extension past 5/20/2020 to conduct Boiler MACT 5 year tune-up due to GM shutdown during COVID-19 pandemic. Print email and letter for file. AQD email of 3/31/2020 clarifies that the 3/24 letter is indeed acceptable as the advance notification. Print email for file.

Name: Daniel Marie Date: 9/15/2020 Supervisor: 8.W.