DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: Telephone Notes

B1	8242762	7

<u> </u>			
FACILITY: Morton Salt, Inc.		SRN / ID: B1824	
LOCATION: 180 Sixth St., MANISTEE		DISTRICT: Cadillac	
CITY: MANISTEE		COUNTY: MANISTEE	
CONTACT: Don Kuk , Environmental Manager		ACTIVITY DATE: 10/20/2014	
STAFF: Caryn Owens	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MAJOR	
SUBJECT: Annual Shut-down was 10	/13-10/17, upon start-up of the boiler on natural g	gas, the COMS reported a steady opacity of 40%,	
when they started coal, the opacity sta	yed the same. Had a technician service the syste	em, and exterior filters were wet and dirty. Changed	
them and opacity was normal again.	·		
RESOLVED COMPLAINTS:		•	

Morton Salt had Annual Shut-down during 10/13-10/17, upon start-up of the boiler system on natural gas, the COMS reported a steady opacity of 40%, when Morton Salt started up on coal, the opacity stayed the same. Morton Salt had a technician come and service the COM system, and found that the exterior filters were wet and dirty. They changed out the filters and opacity was back to normal again. No excursions happened duing this event. Morton Salt had a ceritified opacity reader do a modified Method 9 to observe the stack while this was happening, and the reader reported no opacity coming from the stack.