DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

| Facility: Michigan Sugar Company, Croswell Factory | SRN: | B2876 |
|---|-------------------|-------------|
| Location: 159 S Howard Ave | District : | Saginaw Bay |
| | County: | SANILAC |
| City: CROSWELL State: MI Zip Code: 48422 Comp Status | liance : | Compliance |
| Source Class: MAJOR State | ff: Sharor | LeBlanc |
| FCE Begin Date: 11/28/2013 FCE Date | Completion e : | 10/28/2015 |
| Comments : | | |
| | | |
| | | |

List of Partial Compliance Evaluations:

| Activity Date | Activity Type | Compliance Status | Comments | |
|---------------|-----------------------------------|-------------------|--|--|
| 10/28/2015 | Scheduled Inspection | Compliance | compliance inspection for fiscal year 2016. Note facility has upcoming stack testing for recently installed boiler to also be conducted in the 2016 fiscal year. sgl | |
| 10/12/2015 | Malfunction Abatement Plan | Compliance | MAP for FGSUGAR to meet permit requirements. Document was edited and resubmitted electronically by consultant per request on 10/13/2015. sgl | |
| 09/29/2015 | ROP Other | Compliance | Nox/O2 CEMS Monitoring Plan | |
| 09/29/2015 | ROP Other | Compliance | Initial riley boiler startup notification- corrected version. Startup was 8/28/2015 not an anticipated 9/29/2015. | |
| 09/24/2015 | CAM Excursions/Exceedan ces | Compliance | No exceedences or excursions reported. | |
| 09/24/2015 | CAM monitor downtime | Compliance | No downtime reported | |
| 09/23/2015 | ROP Semi 1 Cert | Compliance | document appears in order- sgl | |
| 09/08/2015 | ROP Other | Compliance | Notification of Riley Boiler Initial Startup | |
| 09/08/2015 | Malfunction Abatement Plan | Compliance | MAP for Riley Boiler | |
| 08/07/2015 | ROP Other | Compliance | Notification of installation for EURILEYBLR. Document dated August 3, 2015, e-mail CC was received by District on that date. | |

| Activity Date | Activity Type | Compliance Status | Comments |
|---------------|-----------------------------------|-------------------|--|
| 07/01/2015 | ROP Other | Compliance | notification that the 2 wickes coal fired boilers had been rendered inoperable - to meet PTI requirements. submitted during public comment period. sgl |
| 05/15/2015 | Other Non ROP | | Hand delivered request for construction waiver for permit 21-15. Denial letter was sent 5/11/2015 |
| 03/30/2015 | ROP Annual Cert | Compliance | |
| 03/30/2015 | ROP SEMI 2 CERT | Compliance | |
| 03/30/2015 | CAM Excursions/Exceedan ces | Compliance | |
| 03/30/2015 | CAM monitor downtime | Compliance | |
| 02/19/2015 | MAERS | Compliance | Cert form for MAERS received 2/18/2015. MAERS submittal for calendar year 2014 received on 2/11/2015. Approved with changes on 2/19/2015. sgl |
| 11/10/2014 | Other Non ROP | | company response to EPA 114(a) request. |
| 09/17/2014 | ROP Semi 1 Cert | Compliance | |
| 09/17/2014 | CAM Excursions/Exceedan ces | Compliance | |
| 09/17/2014 | CAM monitor downtime | Non Compliance | monitor down for 3 months, not repaired until after campaign. |
| 05/12/2014 | Complaint Investigation | | Odor Survey conducted by rfo as followup on 5/6 & 5/8/2014 odor complaints. |
| 04/24/2014 | MAERS | Compliance | 2013 MAERS cert form submitted 3/3/2014 |
| 03/20/2014 | ROP Annual Cert | Compliance | no exceedances or deviations reported |
| 03/20/2014 | ROP SEMI 2 CERT | Compliance | no exceedances or deviations reported |
| 03/20/2014 | CAM Excursions/Exceedan ces | Compliance | no excursions or exceedances reported |
| 03/20/2014 | CAM monitor downtime | Compliance | No downtime reported |

Name: Should UBlace Date: 12/21/2015-Supervisor: C. Have