## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**FCE Summary Report** 

B4032

Facility :	General Motors LLC - Pontiac North Campi	s SRN: B4032
Location :	850 Glenwood MC: 483-710-106	District : Southeast Michigan
		County: OAKLAND
City:	PONTIAC State: MI Zip Code: 48	340 Compliance Compliance Status:
Source Cla	ss: MAJOR	Staff: Iranna Konanahalli
FCE Begin	Date: 6/6/2017	FCE Completion 6/11/2018 Date:
Comments	: Only BP ULSD (15 ppm S) dyed is used ROP.	l in the generators. GM is in compliance wi

## **List of Partial Compliance Evaluations:**

Activity Date	Activity Type	Compliance Status	Comments
05/24/2018	Scheduled Inspection	Compliance	ROP CMS scheduled FY 2018 inspection of General Motors Pontiac North Campus ("GM")
04/26/2018	MAERS	Compliance	MAERS Report Submission 1. GM Pontiac North Campus B4032 Sec 1 (Metal Center) and 2 (R&D): CY 2017 Semi-annual (Semi2: July-Dec 2017), CAM- 2017 (0 deviation), MAERS-2017 and Annual (Jan-Dec 2017) Cert. received on March 15, 2018— Timely. NIL deviation for Semi-2, Sec1 & Sec2. Compliance for Annual 2017 except Sec1 Metal Center did not report in a timely manner commencement of operation of CycloneSeparator operation.
0472072010		Compliance	1. GM Pontiac North Campu B4032 Sec 1 (Metal Center) (R&D): CY 2017 Semi-ann (Semi2: July-Dec 2017), CA 2017 (0 deviation), MAERS and Annual (Jan-Dec 2017) received on March 15, 2018 Timely. NIL deviation for Se Sec1 & Sec2. Compliance for Annual 2017 except Sec1 M Center did not report in a tin manner commencement of operation of CycloneSepara

B4032 \_ FCE\_ \$5 2018 06 11

Activity Date	Activity Type	Compliance Status	Comments
04/26/2018	ROP Annual Cert	Compliance	1. GM Pontiac North Campus B4032 Sec 1 (Metal Center) and 2 (R&D): CY 2017 Semi-annual (Semi2: July-Dec 2017), CAM-2017 (0 deviation), MAERS-2017 and Annual (Jan-Dec 2017) Cert. received on March 15, 2018—Timely. NIL deviation for Semi-2, Sec1 & Sec2. Compliance for Annual 2017 except Sec1 Metal Center did not report in a timely manner commencement of operation of CycloneSeparator operation.
04/26/2018	ROP SEMI 2 CERT	Compliance	1. GM Pontiac North Campus B4032 Sec 1 (Metal Center) and 2 (R&D): CY 2017 Semi-annual (Semi2: July-Dec 2017), CAM-2017 (0 deviation), MAERS-2017 and Annual (Jan-Dec 2017) Cert. received on March 15, 2018—Timely. NIL deviation for Semi-2, Sec1 & Sec2. Compliance for Annual 2017 except Sec1 Metal Center did not report in a timely manner commencement of operation of CycloneSeparator operation.
04/26/2018	ROP SEMI 2 CERT	Compliance	1. GM Pontiac North Campus B4032 Sec 1 (Metal Center) and 2 (R&D): CY 2017 Semi-annual (Semi2: July-Dec 2017), CAM-2017 (0 deviation), MAERS-2017 and Annual (Jan-Dec 2017) Cert. received on March 15, 2018—Timely. NIL deviation for Semi-2, Sec1 & Sec2. Compliance for Annual 2017 except Sec1 Metal Center did not report in a timely manner commencement of operation of CycloneSeparator operation.

Activity Date	Activity Type	Compliance Status	Comments
04/26/2018	ROP Annual Cert	Compliance	1. GM Pontiac North Campus B4032 Sec 1 (Metal Center) and 2 (R&D): CY 2017 Semi-annual (Semi2: July-Dec 2017), CAM-2017 (0 deviation), MAERS-2017 and Annual (Jan-Dec 2017) Cert. received on March 15, 2018—Timely. NIL deviation for Semi-2, Sec1 & Sec2. Compliance for Annual 2017 except Sec1 Metal Center did not report in a timely manner commencement of operation of CycloneSeparator operation.
04/26/2018	ROP Other	Compliance	MAERS Certification form - Section 1 and 2.  1. GM Pontiac North Campus B4032 Sec 1 (Metal Center) and 2 (R&D): CY 2017 Semi-annual (Semi2: July-Dec 2017), CAM- 2017 (0 deviation), MAERS-2017 and Annual (Jan-Dec 2017) Cert. received on March 15, 2018— Timely. NIL deviation for Semi-2, Sec1 & Sec2. Compliance for Annual 2017 except Sec1 Metal Center did not report in a timely manner commencement of operation of CycloneSeparator operation.
07/28/2017	ROP Other	Compliance	Commencement of Trial Operation of Cyclone Separator
07/18/2017	ROP Other	Compliance	Carbon Monoxide Destruction Efficiency Test Report. Overall CE * DE > 96%. Report received timely and complete.
07/18/2017	ROP Other	Compliance	CO Capture Efficiency Emissions Test Summary Report. Avg 99.53% control efficiency. Report received timely and completeSL

Name: Supervisor: Joyle Bage 3 of 3

			!
•			•
			•
		•	