## DEPARTMENT OF ENVIRONMENTAL QUALITY

## AIR QUALITY DIVISION

## FCE Summary Report

Facility :	Lambda Energy Resources LLC - Mayfield 23					SRN :	B5587	
Location :	Center Rd.						District :	Cadillac
							County :	GRAND TRAVERSE
City: K	KINGSLEY	State:	MI	Zip Code :	49649	Comp Status		Compliance
Source Clas	ss: SM OPT	JUT				Staf	f: Kurt C	hilds
•						FCE Date	Completion	1/27/2021
Comments	:							

## List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments	
01/27/2021	On-site Inspection	Compliance	2021 FCE.	
01/04/2021	Other Non ROP	Compliance	Quarterly monitoring report for PTI 193-08 SC 1.13 received via email. Reported no H2S flow or SO2 emissions this quarter.	
10/08/2020	Other Non ROP	Compliance	Quarterly monitoring report for PTI 193-08 SC 1.13 received via email. Reported no H2S flow or SO2 emissions this quarter.	
07/07/2020	Other Non ROP	Compliance	Quarterly monitoring report for PTI 193-08 SC 1.13 received via email. Reported no H2S flow or SO2 emissions this quarter.	
04/06/2020 Other Non ROP		Compliance	Quarterly monitoring report for PTI 193-08 SC 1.13 received via email. Reported no H2S flow or SO2 emissions this quarter.	
04/01/2020 Self Initiated Inspection		Compliance	Compliance Check Inspection.	
03/05/2020	MAERS	Compliance	See MAERS for further info.	
01/07/2020 Other Non ROP		Compliance	Quarterly monitoring report for PTI 193-08 SC 1.13 received via email. Reported no H2S flow or SO2 emissions this quarter.	