

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : CLOVERLAND ELECTRIC COOPERATIVE - DETOUR	SRN : B6106
Location : 836 HIGHWAY M-134	District : Marquette
	County : CHIPPEWA
City : DETOUR State: MI Zip Code : 49725	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Lauren Luce
FCE Begin Date : 5/23/2022	FCE Completion Date : 5/23/2023
Comments : FCE complete. Facility is in compliance.	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
05/23/2023	On-site Inspection	Compliance	Targeted Inspection FY23
03/13/2023	MAERS	Compliance	SCC codes verified. MAERS emission factor used. Attachment provided.
08/03/2022	MACT (Part 63)	Compliance	Semiannual compliance report for MACT ZZZZ. No deviations reported. Report includes operating hours, fuel used, operational temperature averages, and operation pressure change averages for EUENGINE6 and EUENGINE7.

Name: 

Date: 6-12-23

Supervisor: 