DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: Self Initiated Inspection

B645130477

FACILITY: BACCO CONSTRU	UCTION CO PLANT 12	SRN / ID: B6451		
LOCATION: ASPHALT PLAN	T 12 PERMIT #547-78BG, IRON MOUNTAIN	DISTRICT: Upper Peninsula		
CITY: IRON MOUNTAIN		COUNTY: DICKINSON		
CONTACT: Dan O'Neil, Oper	ator	ACTIVITY DATE: 07/30/2015		
STAFF: Joe Scanlan COMPLIANCE STATUS: Compliance		SOURCE CLASS: SM 208A		
SUBJECT:		The state of the s		
RESOLVED COMPLAINTS:				

INSPECTION DATE: 7/30/2015

DEQ-AQD STAFF: Joseph Scanlan

FACILITY: Baaco Asphalt Plant #12

FACILITY OWNER: Bacco Construction Company

COMPLIANCE STATUS: In compliance

<u>LOCATION</u>: The plant was located at the Keweenaw Land Association pit in Crystal Falls Township, Iron County, just south of US-2 and east of the US-2/Oss Road intersection.

INSPECTION: My contact at the plant was plant operator Dan O'Neil. The plant had not operated since 7/25/2015, 5 days prior to my inspection. Mr. O'Neil presented a copy of permit #547-78BG and logs for waste oil specification and daily operation. The plant had produced 1720.42 tons of total product (190 tons RAP) on the most recent day of production and 15,262.55 tons of total product (2051 tons RAP) for the 2015 season, consuming RAP at approximately 11% the date of inspection and averaging 12.6% over the previous 80 days. No drum or mix temperatures were obtainable as the plant was not operating at the time of inspection.

The baghouse contains 1080 bags total. Mr. O'Neil inspected the baghouse utilizing a tracer compound and a blacklight and changed 90 bags on 5/20/2015 and the last visual inspection was on 6/15/2015 when the plant arrived at its current location. Baghouse photohelic gauge readings in the log book averaged a differential pressure of .45 for the last 40 days. There were spare bags on site.

SUMMARY: No violations of the Air Pollution Control Rulers or PTI #547-78BG were observed during this inspection.





Image 1(B121): Bacco portable asphalt plant #12



lmage 2(B122) : Storage silo w/conveyor for Bacco portable asphalt plant #12




Image 3(B123): Operators log




Image 4(B124): Oil sampling analysis

		4402
STRAIGHT	BILL OF LAD	ING - SHORT FORM
		ING - SHOHI FORM
	ENVIRONMENT	AL, INC.
··· (1) [4] [4] [4] [4] [4] [4] [4] [4] [4] [4]	ADGER-ROAD • KA EPA # WIDGE EMERGENCY # 1-6	UKAUNA-WI-64130-T-RICLORD 580298 / TROOCOLING TO 500-822-8218
SHIPTO BACC	<u> </u>	DATE 7-17-15
PLANT #	CITY/STATE	11/14/12/14 11/1
CUSTOMER EPA # _		
CARRIER 54	· · · Ladition	12 Carrier 12
TRACTOR #	. 17	TRAILER # 22
PRODUCT:		
PETROLEUM U	SED OIL, N.O.S., CLASS	9, PG III, (BURNER FUEL)
COMBUSTIBLE	LIQUID, N.O.S., NA 19	93, PG III, (CONTAINS USED CIL)
THIS IS TO CERTIFY YEAT THE PACKAGED, MAPRIED, AND ACCORDING TO THE APPLIC	HE HEREIN NAMEO MATER LABELED, AND ARE IN LABLE REGULATIONS OF T	albare properly classified, described, proper condition for transportation he department of transportation.
TEST GROUP 4-10-		IE-LOAD OOO ORDERS IS RECEIVED BY THE CARPAER
THE CONSIGNEE AND THE AND THE TEL	DESTINATION SET PORTI- RIMS AND CONDITIONS OF	AGREES TO TRANSPORT THE PROPERTY TO HEREIN SUBJECT TO THE CLASSIFICATION THE UNIFORM DOMESTIC STRAIGHT BILL OF ASSISTANTION. IN EFFECT ON THE DATE OF
ESSUANCE OF THIS BILL OF PORTATION OF THE PROF FILLES, REGULATIONS AND	FLADING, IT IS FUNTHER ENTY WILL BE PERFORI LAWS.	ACREED BY THE CARREST THAT THE TRANS- RED IN COMPLANCE WITH ALL APPLICABLE
model, recording to the	· ·	AGREED BY THE CARRIER THAT THE TRANS- RED IN COMPUNICE WITH ALL APPLICABLE
BSUANCE OF THIS BILL OF PORTATION OF THE PROF RIJLES, REGULATIONS AND DRIVER'S SIGNATU	· ·	I NEPIEN SURVICEY TO THE CLASSIFICATION; THE UNIFORM COMESTIC STRAIGHT BILL OF ASSISTANTION. IN EFFECT ON THE DATE: OF AGREED BY THE CARBERT THAT THE TRANSED IN COMPLIANCE WITH ALL APPLICABLE
THE DESCRIBED M	SCALE PRI	MOUT GALS. 7 688
THE DESCRIBED M	SCALE PRI	GALS. GALS. GOOD 40 CERT Fact 279 and WONG 590"
THE DESCRIBED M	SCALE PRIII ATERIAL OOD TED Speed to EPA. Respeedbook	GALS. GALS. GALS. GOVERN Fact 279 and WONE 590*

Image 5(B125): Purchase receipt for oil

NAME Jusque James	DATE 8 5 15	SUPERVISOR	
	11		

DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility:	BACCO CONSTRUCTION CO PLANT 12			SRN:	B6451		
Location :	ASPHALT PLAN NORTH HIGHW		MIT #547-7	8BG N36	76	District :	Upper Peninsula
					ſ	County:	DICKINSON
	RON IOUNTAIN	State: MI	Zip Code :	49801	Compl Status		Compliance
Source Class: SM 208A Staff: Joe Scanlan					anlan		
FCE Begin Date: 1/1/2015 FCE Completion 8/5/2015 Date:							
Comments: FCE completed 8/5/2015							

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
07/30/2015	Self Initiated Inspection	Compliance	
06/16/2015	Relocation Notification	Compliance	Relocation of portable asphalt plant from Portage Twp in Houghton County to Crystal Falls Twp in Dickinson County from 6/15/2015 to 8/30/2015.

Name: Date: 8 5 2015 Supervisor:
Page 1 of 1