



AMERICAN COLLOID COMPANY
807 AUSITN AVE
ALBION, MI 49224

Phone 517-629-6808
Fax 517-629-4813

Date: 12-15-16

**Mr. Rex Lane
MDEQ Air Quality Division
Kalamazoo District Office
7953 Adobe Road
Kalamazoo, MI 49009**

Subject: Violation Notice dated 11-29-16, SRN: B7010 Calhoun County

Attention: Rex Lane

In response to the violation notice from you visit on 11-09-16, regarding the Federal Clean Air Act: Part 55, Air Pollution Control of the Natural Resources & Environmental Protection Act 1994 PA 451.

1. Truck loadout PTI # 326-88 Special Condition #22: We have on order more hose to replace any that are cracked or torn tubing. We have a couple of tanks that are not in use so they don't have any hose on them. These will be checked monthly and replaced as needed. Completed when the materials come in.
2. Kice Collector PTI #326-88 SC #18: Relocate differential pressure gauges to ground level. This was to be done by 11-30-1998. It has been ongoing since a letter dated 10-14-1998. We have ordered the material to bring the gauges to ground level .This will be completed when all material is here. We should have them done by 01-19-17.
3. Fugitive Dust Control Plan: Our facility will record pressure differential on a monthly basis for all baghouses, check for visible emissions and clogged lines, maintain an updated spare parts inventory listing. Sweeping daily of the roadway from our plant to the entrance to the street stated in the plan will be updated. We don't have a sweeper large enough to handle this task. With the less traffic from Harvard Industries we don't have the issues with as much mud and dirt in the drive. Will prepare and submit a revised FDCP by January 20, 2017.
4. Mikropul Baghouse Collector PTI #327-88 #20: Relocate differential pressure gauges to ground level. This was to be done by 11-30-1998. It has been ongoing since a letter dated 10-14-1998. We have ordered the material to bring the gauges to ground level .This will be completed when all material is here. We should have them done by 01-19-17.
5. Mikropul 16-N-6 Collector PTI #327-88 #21: We will be checking out the dust coming from our Tanks 2&3 for any dusting and check the dust collector. Observed dust from the middle truck loud out bay. This could have come from a Shute that could be replaced. We are checking into a new one to be sure the electrical will work with what we have now. If it works we will have to order the part and have our electrician come and complete the job. Should be completed by January 31, 2017 as long as the part comes in and schedule the electrician.

Annette Collier
Plant Manager
American Colloid Company
Minerals Technologies Inc.
807 Austin Avenue
Albion, MI 49224
517-629-6808
517-629-4813 fax.

