RESOLVED COMPLAINTS:

DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: Self Initiated Inspection

Sprngs12 /Blue Lk/ Cold Sprngs 1	SRN / ID: B7198
MANCELONA	DISTRICT: Gaylord
	COUNTY: KALKASKA
	ACTIVITY DATE: 11/10/2014
COMPLIANCE STATUS: Compliance	SOURCE CLASS: MAJOR
	MANCELONA

AQD staff was notified by the permittee the Blue Lake facility would be completing valve maintenance on the two 36 inch lines.

Torello, AQD, met Mr. Rundal and Mr. Dennis Myas at the facility. The valve work was needed because there was a leak on the lines and a positive seal is needed. To complete the work, the pipelines in the well field were blown down. The blown down gas was burned structure designed for burning blown gas. The project will take approximately two weeks to complete.

While on site AQD staff did not smell any gas.