## DEPARTMENT OF ENVIRONMENTAL QUALITY

## AIR QUALITY DIVISION

## FCE Summary Report

Facility :	FCA US LLC Sterling Heights Assembly plant SRN :			B7248
Location :	38111 Van Dyke CIMS 450-34-00		District :	Southeast Michigan
		ſ	County :	MACOMB
City : S	STERLING HTS State: MI Zip Code	: 48312 Compl Status		Compliance
Source Cla	ss: MAJOR	Stafi	f: Rem l	Pinga
FCE Begin	Date : 9/1/2017	FCE Date	Completion :	9/27/2018
Comments	: No deviation observed during ins	pection		
Comments	: No deviation observed during ins			

## List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments	
09/21/2018 ′	ROP Semi 1 Cert	Compliance	ROP Semi1 Certification received on time. No deviations were reported.	
09/21/2018	CAM Excursions/Exceedan ces	Compliance	FG-CAM: The company reported no Compliance Assurance Monitoring (CAM) excursions or exceedances during the reporting period.	
09/21/2018	MACT (Part 63)	Compliance	Semi-Annual Compliance Report for Surface Coating of Autos and Light Duty Trucks (Auto MACT) and Boiler MACT. Notification of compliance status under 40 CFR 63 Subparts A and IIII for South Paint Shop. Initial Compliance Period - mid March to April 30, 2018. No deviations reported.	
08/29/2018	Stack Test Observation	Compliance	RICE Emergency Generator West of South Paint Shop	
08/28/2018	Stack Test Observation	Compliance	Stack Test Observation	
08/09/2018	ROP Qrtly Cert	Compliance	Second Quarter 2018 Emissions Report. No deviation observed.	
07/16/2018	Scheduled Inspection	Compliance	Level 2 Scheduled Inspection	
05/21/2018	MAERS	Compliance	MAERS Report Submission. Audit completed 5/21/2018.	
05/14/2018	ROP Other	Compliance	- NESHAP Initial Notification for Stationary Reciprocating Internal Combustion Engine - PTI No. 27-17B, FG-NSPS JJJJ, SC VII.4.	

Activity Date	Activity Type	Compliance Status	Comments	
05/03/2018	ROP Qrtly Cert	Compliance	First Quarter 2018 Emissions Report. No deviations observed.	
05/02/2018	Telephone Notes	Compliance	Telephone Call	
04/20/2018	Malfunction Abatement Plan	Compliance	Revised Malfunction Abatement Plan Updated to incorporate changes to the facility per PTI 27-17A issued November 2, 2017. AQD staff discussed with FCA-SHAP Mr. Sanni about additional revisions in the MAP.	
02/28/2018	ROP Other	Compliance	Notification of installation completion and start of trial operations per PTI No. 27-17A, S.C. FG-SOBL(VII.1); MI-ROP- B7248-2014a, and MI Rule 336.1216(1)(a)(v)(A).	
02/20/2018	ROP Qrtly Cert	Compliance	4th Quarter 2017 Emissions Report. No deviations reported. Plant reported as "on extended production shutdown due to new product launch".	
02/20/2018 ,	ROP Other	Compliance	On 2/12/2018, AQD Warren Office received letter of notification of start-up and trial operation of North (Box) Paint Shop, dated 2/07/2018, of one of 2 planned lines as required in PTI No. 27- 17A, MI-ROP-B7248-2014a, and AQD Administrative Rule R 336.1216(1)(a)(v)(A).	
02/12/2018	Other	Compliance	Notification of Start-up and trial operation for Box Paint Shop line1.	
11/30/2017	Other	Compliance	EU-Boiler1, 2, & 3 Stack Test Protocol Received.	
11/13/2017	ROP Qrtly Cert	Compliance	Third Quarter 2017 Emissions Report. Report submitted on time and no deviations reported.	
11/13/2017	NSPS (Part 60)	Compliance	Startup Notification for Hot Water Generators (Subpart Dc) and South Paint Shop Operations (Subpart MM).	
09/18/2017	ROP Semi 1 Cert	Compliance	ROP Semi1 Certification received on time. No deviations were reported.	

Name: <u>L'[1]</u> Date: <u>9/27/2018</u> Supervisor: <u>1940</u> <u>26</u> Page 2 df 2

•