

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection 

B753624418

FACILITY: HILLSDALE CITY OF PUBLIC UTILITIES		SRN / ID: B7536
LOCATION: 201 WATERWORKS AVE, HILLSDALE		DISTRICT: Jackson
CITY: HILLSDALE		COUNTY: HILLSDALE
CONTACT:		ACTIVITY DATE: 02/25/2014
STAFF: Brian Carley	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MAJOR
SUBJECT: Scheduled Inspection		
RESOLVED COMPLAINTS:		

Facility: Hillsdale Power Plant
 Facility Address: 201 Waterworks Avenue, Hillsdale, MI
 Contact Person: Mike Barber, Production Supervisor (Ph: 517-437-6416)
 Email: mbarber@hillsdalebpu.com

I arrived at the facility and met with Mike Barber to conduct a scheduled inspection to determine compliance with their ROP. When I arrived, none of the engines were running. Mike told me that the last engines to run were #5 and #6 at the end of August 2013. Engines 2, 3, and 4 did not run at all last year (see attached required recordkeeping for Engine 3). Diesel Engine Generators Nos. 7, 8, 9, and 10 were removed from this facility in 2009 (No. 7) and 2011 (Nos. 8, 9, 10). Mike told me that they were looking at dismantling and removing the remaining engines sometime in the near future. I told him that once they permanently disconnected the engines from the fuel supply they could request to void their ROP. He then provided all the records that he was required to keep. Based on the information that I received during this inspection, I determined that they are in compliance with their ROP. I thanked Mike for his time and left.

NAME  DATE 4/5/14 SUPERVISOR 