

B9050
MHWL

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

B905046013

FACILITY: BUCKEYE TERMINALS LLC -DETROIT TAYLOR TERMINAL		SRN / ID: B9050
LOCATION: 8000 BEECH DALY RD S, TAYLOR		DISTRICT: Detroit
CITY: TAYLOR		COUNTY: WAYNE
CONTACT:		ACTIVITY DATE: 09/10/2018
STAFF: C. Nazaret Sandoval	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: FY 2018 Scheduled Inspection		
RESOLVED COMPLAINTS:		

OBSERVATIONS

I arrived at the site located at 8000 Beech Daly Road, Taylor, MI at about 10:40 a.m. There is no sign with a business name anywhere. Staffs from the Buckeye Pipe Line Holding, LP - Taylor Terminal (Mr. Brad Crawford, Sr. Operations Manager/ Wayne Pipeline & Terminal Asset Team and Mr. Richard A. Zeestraten, Terminal Operator) let me in the property. We walked around the site for about 10 minutes and they showed me the storage tanks and the location of the of the former loading rack. There are seven tanks still standing, but they are completely disconnected and partially rusted.

The office building and the loading rack have been demolished years ago. There is only one white standing building near the southwest side of the property, east of Beech Daly Rd. and near the railroad track. I was told that the building is used for storage of electrical gear. Buckeye still provides cathodic protection to the tanks. Underground cables are still connected to the source of electrical power.

Even though the operations at the site have ceased years ago, AQD will maintain this facility listed on MACES as an "active site" as long as the tanks remain standing on the site. Buckeye has to remove all permitted equipment from the site and make them inoperable before AQD could modify the status and void the active permits.

NAME C. Sandoval

DATE 9/25/2018 SUPERVISOR JK