DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility:	ty: Lambda Energy Resources, LLC - Charlton 4		SRN:	B9144
Location: 5750 LOST CABIN TR			District :	Gaylord
			County:	OTSEGO
City:	JOHANNESBUR State: MI Zip Code G	49751 Comp Statu	oliance s :	Compliance
Source Cla	ass: SM OPT OUT	Sta	ff: Bill Ro	gers
FCE Begin	n Date : 9/18/2018	FCI Dat	E Completion e :	9/18/2019
Comments	s:			

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
09/18/2019	Scheduled Inspection	Compliance	Compliance inspection and record review
03/08/2019	MAERS	Compliance	2018 MAERS, Check MAERS for any review comments

Name William J. Roger J. Date:	9/28/19	Supervisor:	30
			Dogo 1 of 1

Page 1 of 1