

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
**ACTIVITY REPORT: Self Initiated Inspection**

B916153173

<b>FACILITY:</b> Lambda Energy Resources LLC - Mayfield 16		<b>SRN / ID:</b> B9161
<b>LOCATION:</b> 3271 HARRAND RD, MAYFIELD		<b>DISTRICT:</b> Cadillac
<b>CITY:</b> MAYFIELD		<b>COUNTY:</b> GRAND TRAVERSE
<b>CONTACT:</b>		<b>ACTIVITY DATE:</b> 04/01/2020
<b>STAFF:</b> Kurt Childs	<b>COMPLIANCE STATUS:</b> Compliance	<b>SOURCE CLASS:</b> SM OPT OUT
<b>SUBJECT:</b> Compliance check inspection.		
<b>RESOLVED COMPLAINTS:</b>		

**Compliance Check Inspection  
Lambda Energy Resources LLC  
B9161 Mayfield 16 CPF**

This inspection was conducted to fulfill the AQD's responsibility to ensure protection of the public health under the limitations inherent during the COVID 19 disease outbreak. This inspection was observational in nature and did not involve any face to face contact with source employees.

While in the area for a scheduled inspection on April 1, 2020, I conducted a compliance check inspection of the Mayfield 16 CPF and observed the following:

**PTI or ROP:** PTI 634-96B

**Facility Operating Status:** Operating

**Equipment Operating:** Well pump jack, Tanks and VRU, 1 compressor/engine (natural gas fired), 1 Glycol Dehydrator.

**Any Visible Emissions?:** No

**Any Odors?:** Mild odors downwind of the dehy and tanks.

**Any Unusual Activities (new construction, new equipment, evidence of spills, etc.)?:** Plant operators were on-site but were not contacted.

**Any Compliance Concerns:** No.

NAME 

DATE 4-1-20

SUPERVISOR 