DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY RE	PORT: On-site	Inspection
--------------------	---------------	------------

COLFIGNI CACCALIC CANID AL ECCAMADA	FACILITY: UPPER PENINSULA CONCRETE PIPE CO	
LOCATION: 6480 US 2 AND 41, ESCANABA		DISTRICT: Marquette
CITY: ESCANABA		COUNTY: DELTA
CONTACT: Jordan LaCombe , Plant Manager		ACTIVITY DATE: 07/22/2021
STAFF: Sydney Hewson COMPLIA	ANCE STATUS: Compliance	SOURCE CLASS: MINOR

On July 22, 2021 I (Sydney Hewson) performed an onsite inspection of Upper Peninsula Concrete Pipe Co. located at 6480 US-2 in Escanaba MI. While onsite I met with Jordan LaCombe, Plant Manager at Upper Peninsula Concrete Pipe Company. Mr. LaCombe gave me a tour of the facility and showed me the permitted processes.

Facility Description:

UP Concrete Pipe Company manufactures precast stream crossings, precast storm pipes, manholes and catch basins. The Escanaba facility only manufacturers dry cast products, mostly manholes. They operate a dry cast batch cement plant and storage silo.

PTI 93-76:

DODAGEDAGE

Below is an outline of the requirements of PTI 93-76 and a summary of the facilities compliance:

During my inspection there were no visible particulate emissions from the cement handling operations or the cement silos. The facility uses water truck to suppress dust every two days.

Compliance determination:

At the time of my inspection, it appeared UP Concrete Co. was in compliance with PTI 93-76 and all other applicable state and federal air quality regulations.

DATE 0/5/2\ SUPERVISOR EAL