14912 MANILA-FOE

DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility :	Beaumont Hospital - Dearborn						SRN:	J4912
Location :	ation: 18101 OAKWOOD BLVD						District :	Detroit
							County:	WAYNE
City:	EARBORN	State:	MI	Zip Code:	48124	Compl Status		Compliance
Source Class: SM OPT OUT Staff: Todd Zynda								
						FCE Date	Completion :	4/16/2019
Comments :								

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
04/16/2019	Scheduled Inspection		April 16, 2019 Inspection and Visual Emissions Testing

Name: Date: 6/3/19 Supervisor: Page 1 of 1