# DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Scheduled Inspection** 

FACILITY: MARATHON PIPELIN	IE CO	SRN / ID: M4045		
LOCATION: 131 E MOSHERVILI	LE RD, JONESVILLE	DISTRICT: Jackson		
CITY: JONESVILLE		COUNTY: HILLSDALE		
CONTACT:		ACTIVITY DATE: 02/05/2019		
STAFF: Stephanie Weems	COMPLIANCE STATUS: Compliance	SOURCE CLASS:		
SUBJECT: Scheduled inspection	of Marathon Pipeline Co.			
RESOLVED COMPLAINTS:	,			

Minor Source: Scheduled inspection of Marathon Pipeline Co. M4045/Hanover Pipeline-Rainbow Oil Company A9832

### **Purpose**

MADA547722

On, February 5, 2019 I conducted an unannounced compliance inspection of Marathon Pipeline Co./Hanover Pipeline-Rainbow Oil Co., located in Hillsdale, Ml. I was accompanied by Brian Carley of the AQD Jackson Field Office. The purpose of the inspection was to determine the facility's compliance status with the applicable federal and state air pollution regulations, particularly Michigan Act 451, Part 55, Air Pollution Control Act and administrative rules.

## **Facility Location**

The facility is located at 1231 E Mosherville Rd. in Jonesville, MI (Hillsdale county). It is in a rural area. See Image 1 for an aerial photo.

## **Facility Background**

This facility is comprised of an unmanned, above ground, storage tank with a capacity of 54,000 barrels located on the north side of Mosherville Road.

The facility was last inspected July 11, 2018. At that time, it was documented as permanently closed. It is suspected that this site was added to the inspection list again because of confusion with the state registration number (SRN). Previously, the facility was owned by Marathon Pipeline (M4045). During the compliance inspection conducted in September of 2010, AQD staff noted that the facility was closed but had been sold to Hanover Pipeline/Rainbow Oil Company (A9832) who also owns the two buildings across the street. Therefore, information for this location is now under two SRNs.

## Regulatory Applicability

No active permits on file with AQD.

#### **Onsite Inspection**

We arrived at the facility at 11:17AM in order to verify that it was permanently closed. The area around the storage tank and the buildings is run-down and in disrepair. See attached photos.

#### Compliance Summary

Based upon the facility inspection, it is recommended that this facility be removed from further inspection lists and marked as permanently closed.




Image 1(Aerial View): Aerial photo



Image 2(Tank): Storage tank



NAME SHIM WHY DATE 2.6.19

*		*	