

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: Self Initiated Inspection

N073028342

FACILITY: KAMAX L P HAMTRAMCK		SRN / ID: N0730
LOCATION: 3120 DENTON ST, HAMTRAMCK		DISTRICT: Detroit
CITY: HAMTRAMCK		COUNTY: WAYNE
CONTACT:		ACTIVITY DATE: 01/23/2015
STAFF: Jorge Acevedo	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT:		
RESOLVED COMPLAINTS:		

COMPANY NAME : Kamax G.B. Dupont L.P.
 FACILITY ADDRESS : 3120 Denton Street , Hamtramck, MI 48211-1416
 STATE REGISTRAT. NUMBER : N0730
 SIC CODE : 3398
 EPA SOURCE CLASS : B
 EPA POLLUTANT CLASS : 0
 LEVEL OF INSPECTION : PCE
 DATE OF INSPECTION : 1/23/15
 TIME OF INSPECTION : 11:00 AM
 DATE OF REPORT : 2/5/15
 REASON FOR INSPECTION : Self- Initiated Inspection
 INSPECTED BY : Jorge Acevedo
 PERSONNEL PRESENT : Matt Essian, Facility Manager, Hamtramck Recycling
 FACILITY PHONE NUMBER : 313-871-5000
 FACILITY FAX NUMBER :

INSPECTION NARRATIVE:

On January 23, 2015, I conducted a self initiated inspection of Kamax-G.B. Dupont. The basis of the inspection was to verify that equipment at the building was inoperable. During the 2014 MAERS reporting, Kamax stated that they had vacated the facility located at 3120 Denton Street. I determined that the new owner of the building was the facility next door, Hamtramck Recycling.

I contacted Matt Essian, Facility Manager, of Hamtramck Recycling to schedule an inspection of the building located at 3120 Denton Street. I asked what the status of the building was and he explained that they not using the equipment and using the building for storage. I explained that there were active permits assigned to that building. I explained that based on his summary of the building, I could probably void out the permits after verifying that they were inoperable.

I arrived at 11:00 and met with Mr. Essian. I explained the purpose of the visit. Mr. Essian introduced me to two of his staff, McClain and Josh, and said that they would take me to the building.

We walked into the building that formerly housed Kamax. I observed no activity from any of the equipment used by Kamax. I observed several piles of paper. Josh explained that they were using the

building for storage. I observed the area where the washing process occurred. The equipment was gone. Next, we went into the area where the furnaces were located. I observed the two furnaces. They were not active and as Josh explained, the gas line and electricity were cut and they were in the process of recycling the metal. I also saw that some of the ductwork was removed. After observing the equipment, I walked back to Hamtramck Recycling's facility and signed out. I left the facility at 11:30AM.

FACILITY BACKGROUND:

Kamax – GB Dupont is a metal heat treating facility. The facility mostly heat treats metal fasteners (bolts, screws, nuts, etc). The facility has sold the building and the equipment is inoperable. The PTIs assigned to Kamax will be voided.

COMPLAINT/COMPLIANCE HISTORY:

NA

OUTSTANDING CONSENT ORDERS:

None

OUTSTANDING LOVs

None

OPERATING SCHEDULE/PRODUCTION RATE:

NA

APPLICABLE RULES/PERMIT CONDITIONS:

Permits C7448-7449(November 17, 1986) and C6284(February 2, 1983) will be voided.

APPLICABLE FUGITIVE DUST CONTROL PLAN CONDITIONS:

N/A


MAERS REPORT REVIEW:

NA

FINAL COMPLIANCE DETERMINATION:

Kamax is no longer operating at the Hamtramck facility. The equipment was observed to be inoperable. The Permits to Install for the equipment will be voided.

NAME



DATE

5-23-15

SUPERVISOR

