DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Off-site Inspection

N128265938		
FACILITY: Marathon Oil (GW contamination M-115 and M-55)		SRN / ID: N1282
LOCATION: 6541 E M-115, CADILLAC		DISTRICT: Cadillac
CITY: CADILLAC		COUNTY: WEXFORD
CONTACT:		ACTIVITY DATE: 12/14/2022
STAFF: Caryn Owens	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Inspection for PTI 537-85		
RESOLVED COMPLAINTS:		

Caryn Owens of the Department of Environment, Great Lakes, and Energy (EGLE) – Air Quality Division (AQD) had a scheduled field inspection of Marathon Oil (N1282) due to groundwater contamination formerly located at 6441 East M-115 in Cadillac, Wexford County, Michigan. The purpose of this inspection was to determine the facility's compliance with Permit to Install (PTI) number 537-85. The facility is considered a minor source of air pollution.

Source Description

This site was a source of groundwater contamination discovered in June 1986. The facility obtained PTI 537-85 which was for five spray irrigation heads for groundwater cleanup from gasoline components from leaking underground storage tanks. Based on records reviewed from EGLE – Remediation and Redevelopment Division (RRD), the contamination did not appear to be a large area. AQD viewed the facility location of 6441 East M-115 Street via Google Earth Map, and the historical mapping data. The site has changed quite a bit from when the PTI was initially permitted. Based on the closure report AQD reviewed from EGLE-RRD, dated October 13, 2017, the site had a total 11,850 cubic yards of soil removed from the site, and approximately 10,043,950 gallons of groundwater remediated. The structures and remediation system are no longer on-site, and the site is now developed as residential with a new house constructed on site. According to RRD correspondence, monitoring wells were removed, and the site has been closed.

Based on the information reviewed and observed, the spray irrigation system has been removed from the site, and therefore PTI 537-85 can be voided.

(augu (mens NAME

DATE _____

SUPERVISOR