

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : Merit Energy Company - Mentor Gas Plant	SRN : N1397
Location : 745 E. Hughes Lake Rd.	District : Gaylord
	County : OSCODA
City : UNION CORNERS	State: MI Zip Code : 48654 Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Bill Rogers
FCE Begin Date : 6/21/2017	FCE Completion Date : 6/21/2018
Comments :	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
06/21/2018	Scheduled Inspection	Compliance	Scheduled inspection
03/05/2018	MAERS	Compliance	2017 MAERS, see MAERS for any review comment
02/02/2018	NSPS (Part 60)	Compliance	Semi Annual Report for NSPS. Leak detection summary. Operator claims there were no leaks.
08/16/2017	NSPS (Part 60)	Compliance	40 CFR Part 60, Subpart KKK reporting for the Mentor Gas Plant for the six-month period ending December 2016. The submittal indicates no leaks were observed during the reporting period.

Name: William J Rogers Date: 6/28/18 Supervisor: _____