

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N155029256

FACILITY: BIRCH MACHINERY CO		SRN / ID: N1550
LOCATION: 11160 DIXIE HWY, BIRCH RUN		DISTRICT: Saginaw Bay
CITY: BIRCH RUN		COUNTY: SAGINAW
CONTACT: Harold Johnson ,		ACTIVITY DATE: 04/28/2015
STAFF: Gina McCann	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Inspection of PTI 183-87		
RESOLVED COMPLAINTS:		

I (glm) arrived on site at approximately 9:30 A.M. I met with Mr. Harold Johnson. The facility has one active permit (183-87) for a paint booth and associated equipment. The facility has removed the equipment and no longer has it on site. The company used to paint racks for the auto industry and has since moved away from that work. A request to void the permit was sent to S. Thelen on 4/29/2015.

They are a tool and die shop. I toured the facility with Mr. Johnson and the equipment on site was all exempt from permitting. At the time of my inspection, the facility appeared to be clean and operating well.

NAME Gina L. McCann DATE 4/29/2015 SUPERVISOR C. Kane