## DEPARTMENT OF ENVIRONMENTAL QUALITY

## AIR QUALITY DIVISION

## FCE Summary Report

Lapeer Plating & Plastics, Inc.			SRN :	N1863		
395 DEMILLE RD.					District :	Lansing
				Ĭ	County :	LAPEER
_APEER State	: MI Z	ip Code :	48446			Non Compliance
ss: SM OPT OUT				Staf	f: Natha	niel Hude
Date : 4/28/2014					•	8/11/2015
: Non compliant du	ie to mul	tiple viola	tions with	h contro	l equipment	t.
1	395 DEMILLE RD. APEER State ss : SM OPT OUT Date : 4/28/2014	395 DEMILLE RD. APEER State: MI Z ss : SM OPT OUT Date : 4/28/2014	395 DEMILLE RD. APEER State: MI Zip Code : ss : SM OPT OUT Date : 4/28/2014	395 DEMILLE RD. APEER State: MI Zip Code : 48446 ss : SM OPT OUT Date : 4/28/2014	395 DEMILLE RD. APEER State: MI Zip Code : 48446 Compl Status ss : SM OPT OUT Stafe Date : 4/28/2014 FCE Date	395 DEMILLE RD. District :   County : County :   APEER State: MI Zip Code : 48446 Compliance Status :   ss : SM OPT OUT Staff : Natha   Date : 4/28/2014 FCE Completion Date :

## List of Partial Compliance Evaluations :

Ŧ

- 5

Activity Date	Activity Type	Compliance Status	Comments	
05/22/2015	MAERS	Compliance	Initial received 3/13/15, Audit failed on 5/4/15 due to no supporting data for EU- CHROMEPLATE32 emission calculations, email notification sent to contact. Resubmitted on 5/21/15 using MAERS EF's and approved on 5/22/15.	
04/29/2015	Scheduled Inspection	Non Compliance	Inspection of permitted equipment. EU-CHROMEPLATE32: scrubber in-op, dynes/cm measurements out of compliance 7 days during March and April; EU- CHROMEETCH: 3 magnehelic gauges out of compliance ranges, leak at entry of scrubber; FG- COATING: no pressure test caps for HPLV.	
03/16/2015	MACT (Part 63)	Compliance	On-going compliance status report, 40 CFR Part 63, Subpart N. Decorative Chrome Tank 32 operated 3232 hours w/< 35 dynes surface tension. Summary only required if non-compliance.	
02/24/2015	ROP Qrtly Cert	Compliance	VOC quarterly report. 3.4 tpy/year. Limit is 10/30. Approximately 7.2 tpy on EGPaintLine #2.LP&P does not need to certify any longer.	
08/01/2014	MACT (Part 63)	Compliance	On-going compliance status report, 40 CFR Part 63, Subpart N. Decorative Chrome Tank 32 operated 3379 hours w/< 35 dynes surface tension. Summary only required if non-compliance.	

Activity Date	Activity Type	Compliance Status	Comments
08/01/2014	ROP Qrtly Cert	Compliance	Larry Gatt RO.

Name:  $\frac{1}{1}$  Date:  $\frac{3}{11}$   $\frac{15}{15}$  Supervisor:  $\frac{1}{15}$  Page 2 of 2