## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

FACILITY: ZAREMBA EQUIPMENT INC		SRN / ID: N2355
LOCATION: 8804 M 32 W, ELMIRA		DISTRICT: Gaylord
CITY: ELMIRA		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 06/16/2015
STAFF: Bill Rogers	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Site inspection- fa	cility shut down	
RESOLVED COMPLAINTS:	4	

On June 16, 2015, I inspected the former site of Zaremba Equipment in Elmira. Their main building partially burned down several years ago. They have a permit 999-89, for a multi-oil furnace.

There are still several barns on site. The front end of the main building still stands but it has no wall on the north side. It is being used as a shed to store farm equipment. There is no evidence of a furnace in it.

I went to Zaremba Equipment's new site in Gaylord. I spoke to Mr. Frank Zaremba, brother of the company president Jim Zaremba. Frank Zaremba confirmed that there was a waste oil furnace in their main building in Elmira. It was destroyed in the fire. What was left of it was scrapped.

I told him that we would void the permit for the furnace, since it has been scrapped. He suggested the correspondence for this should go to his brother:

Jim Zaremba, Zaremba Equipment Inc., 1734 Dickerson Road, Gaylord MI 49735

I have sent an email to Permits Section explaining that the equipment has been scrapped and requesting that Permit 999-89 be voided.

NAME William J Rogers Jr.

DATE \_\_\_\_\_\_ SUPERVISOR\_