11047700046

## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Scheduled Inspection** 

N247729915		
FACILITY: MOYLE CONCRETE - HOUGHTON		SRN / ID: N2477
LOCATION: HIGHWAY WEST M-26, HOUGHTON		DISTRICT: Upper Peninsula
CITY: HOUGHTON		COUNTY: HOUGHTON
CONTACT: ED MARCOTTE , OPERATOR		ACTIVITY DATE: 06/18/2015
STAFF: Joel Asher	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Concrete batch plant.		
RESOLVED COMPLAINTS:		

On 6/18/2015 I conducted an unannounced inspection of this facility. My contact was Mr. Ed Marcotte, the plant operator.

To date, the plant has produced about 1000 cubic yards of concrete this year. The site has 2 silos, one for slag and one for Portland cement. Each silo has its own baghouse. Mr. Marcotte stated they inspected the baghouses 2 days ago and routine inspections are done every few weeks. A few bags were replaced and a dozen spare bags are kept on hand.

Discussions were held with Mr. Marcotte regarding inspecting the baghouse and pressure relief on top of the silos after filling the silo to make certain the bags have not been compromised during the filling process.

Mr. Marcotte stated the plant has changed names and is now called Great Lakes Mineral Works Valley View Concrete.

No violations of the Air Pollution Control Rules or PTI #265-90A were observed during this inspection.

NAME full 5

DATE 6/25/15

SUPERVISOR