DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Self Initiated Inspection

FACILITY: Breitburn - Houck 2-17		SRN / ID; N2592
LOCATION: NW T26N R10W Sec 17, EAST BAY TWP CITY: EAST BAY TWP		DISTRICT: Cadillac COUNTY: GRAND TRAVERSE
STAFF: Shane Nixon	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: On-site inspection		· · · · · · · · · · · · · · · · · · ·
RESOLVED COMPLAINTS:	· <u>· · · · · · · · · · · · · · · · · · </u>	

AQD staff traveled to the Houck 2-17 well site with the intent to inspect the soil remediation system associated with Permit to Install No. 561-90. Upon arrival, staff observed that all equipment has been removed from the site. Ms. Carolann Knapp, Breitburn, indicated she was not aware of the permit and sent a void request letter to Lansing.

ston 0 1 NAME

n/16 DATE

SUPERVISOR