

DEPARTMENT OF ENVIRONMENTAL QUALITY  
 AIR QUALITY DIVISION  
 ACTIVITY REPORT: Self Initiated Inspection

N374624306

FACILITY: Kinross Fab. & Machine Inc		SRN / ID: N3746
LOCATION: 17422 S DOLAN STREET, KINCHELOE		DISTRICT: Upper Peninsula
CITY: KINCHELOE		COUNTY: CHIPPEWA
CONTACT: Chuck Esson , President		ACTIVITY DATE: 02/12/2014
STAFF: Joel Asher	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Spray paint booth/area		
RESOLVED COMPLAINTS:		


On 2/12/2014, I conducted an unannounced inspection of this facility. My contact was the president, Mr. Chuck Esson.

The facility continues to operate as a metal fabricating shop. Products are painted in their spray paint area. Filter media is used to control overspray from being blown outside. Filter media was observed to be in place. Spare filter media was onsite and enough was in stock to completely replace the collection area.

A log book has been incorporated to record the amount of paint applied. A sheet is maintained for each calendar month. The amount of paint used is well below 200 gallons per month. The facility will easily qualify for an air use permit exemption under Rule 287.

After the last inspection of this facility on 2/8/2012, Mr. Esson informed employees of the potential asbestos containing materials in the facility. Employees were instructed not to disturb the materials and inform him if there are any issues.

No violations of the Air Pollution Control Rules were observed during this inspection.

NAME 

DATE 2/14/2014

SUPERVISOR \_\_\_\_\_