DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

FACILITY: Total Petroleum, Inc. LOCATION: 236 James St, GRAYLING CITY: GRAYLING CONTACT:		SRN / ID: N5043 DISTRICT: Cadillac COUNTY: CRAWFORD ACTIVITY DATE: 08/28/2018			
			STAFF: Chance Collins	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
			SUBJECT: Scheduled Inspecti	on	
			RESOLVED COMPLAINTS:	an a	

On August 28, 2018 AQD staff traveled to Crawford County to perform an inspection of Total Petroleum Inc. The purpose of the inspection was to determine the facility's compliance with Permit to Install No. 807-93, and applicable state and federal air pollution control regulations. Permit to Install No. 807-93 pertains to a Soil Vapor Extraction (SVE) and groundwater sparge system.

AQD staff arrived on site at 12:35 p.m. to cloudy conditions with a temperature of 73°F and a SW wind of 7 mph. There were no noticeable odors upon arrival.

Upon investigation of site, an SVE and groundwater sparge system no longer exists at this location. The location is currently a Speedway gas station (originally permitted as a "Total Station", with an official address change to 308 S. James St. (AQD staff verified location using plot map within permit). The last correspondence for Permit to Install No. 807-93 recorded was September 7, 1995.

Upon completion of this inspection, AQD staff will recommend Permit to Install No. 807-93 to be voided.

DATE 8/31/2018 SUPERVISOR