

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

N509350387

FACILITY: Woodland Oil - 1050 Garfield Ave		SRN / ID: N5093
LOCATION: 1050 Garfield, TRAVERSE CITY		DISTRICT: Cadillac
CITY: TRAVERSE CITY		COUNTY: GRAND TRAVERSE
CONTACT:		ACTIVITY DATE: 08/16/2019
STAFF: Caryn Owens	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled Inspection		
RESOLVED COMPLAINTS:		

On Friday, August 16, 2019 Caryn Owens of the Department of Environment, Great Lakes, and Energy (EGLE)-Air Quality Division (AQD) attempted to conduct a scheduled field inspection of Woodland Oil – Garfield Road site (SRN: N5093), located at 1050 Garfield Avenue in Traverse City. More specifically, the site is located on the west side of Garfield Avenue at the northwest corner of Carver Street and Garfield Avenue in Traverse City. The field inspection was to determine if there was equipment still located onsite associated with the Permit to Install (PTI) 181-91A.

PTI 181-91A was issued for a soil vapor extraction system to remediate soils contaminated by an underground storage tank leak from 1994. Based on the field inspection and EGLE – Remediation Redevelopment Division (RRD) records, the remediation system has been removed from the Property in 2014. Therefore, based on this information, PTI 181-91A can be voided, and no further action is necessary at this time.

NAME Caryn Owens DATE 9/4/19 SUPERVISOR SN